

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Sundry Notices and Reports on Wells

1. Type of Well OIL	5. Lease Number I-89-IND-57
2. Name of Operator Eastern Petroleum Company	6. If Indian, All. or Tribe Name
3. Address & Phone No. of Operator	7. Unit Agreement Name
4. Location of Well, Footage, Sec., T, R, M 2310' FNL and 1800' FEL; Sec. 3, T-27-N, R-17-W, Unit G,	8. Well Name & Number Table Mesa #2
	9. API Well No. 30-045-20803
	10. Field and Pool
	11. County & State San Juan County, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission	Type of Action	
☐ Notice of Intent	☒ Abandonment	☐ Change of Plans
	☐ Recompletion	☐ New Construction
☒ Subsequent Report	☐ Plugging Back	☐ Non-Routine Fracturing
	☐ Casing Repair	☐ Water Shut off
☐ Final Abandonment	☐ Altering Casing	☐ Conversion to Injection
	☐ Other -	

13. Describe Proposed or Completed Operations

A-Plus Well Service Inc., as contractor, re- entered and then plugged and abandon this well per the attached report.

This work was done for the NMOCD Aztec District Office, contract pending.

14. I hereby certify that the foregoing is true and correct.

Signed William F. Clark Title Contractor Date 3/10/99
William F. Clark

(This space for Federal or State Office use)

APPROVED BY _____ Title _____ Date _____
CONDITION OF APPROVAL, if any:

A - PLUS WELL SERVICE, INC.

P.O. BOX 1979
FARMINGTON, NM 87499
505-325-2627 • FAX: 505-325-1211

March 6, 1999

Oil Conservation Division

State of New Mexico
1000 Rio Brazos Road
Aztec, NM 87410

Re: Plug & Abandonment Report **Table Mesa #2 Well**
NE, 3, 27N, 17W
San Juan County, NM

Cementing Summary:

Cementing #1 with 24 sxs Class B cement to set 7" casing, circulate good cement out conductor.

Plug #1 with 20 sxs Class B cement from 1020' to 920' to cover Dakota interval.

Plug #2 with 36 sxs Class B cement from 600' to 400' to cover Gallup top.

Plug #3 with 25 sxs Class B cement with 2% CaCl₂ from 480' to 350'.

Plug #4 with 91 sxs Class B cement from 385' to surface, circulate good cement out 7" casing.

Plugging Summary:

3-1-99 Road rig and equipment to location, RU. TIH with 8-3/4" bit and 2 drill collars; drill down to 50', circulate well clean. LD power swivel, drill collars and bit. PU 2 joints 2-3/8" tubing and tag at 53'. Spot 50 vis drilling mud in well to surface. TOH and LD tubing. PU 1 joint 7" casing and TIH, land 7" surface casing at 30'. Cementing #1 with 24 sxs Class B cement to set 7" casing, circulate 1 bbl good cement out 13-3/8" conductor. Shut in well and WOC. SDFD.

3-2-99 Safety Meeting. Cut off 13-3/8" conductor pipe and 7" casing to ground level; weld on 7" collar to stub. NU BOP and test. Drill down 40' through cement with 6-1/4" bit. Continue to run in hole with P/S with 8 joints tubing. Circulate well clean at 250'. RD swivel and PU power tongs and 3 joints tubing. LD tongs and PU swivel, drill down to 1020' with 31 joints tubing; circulate hole clean. LD power swivel. Plug #1 with 20 sxs Class B cement from 1020' to 920' to cover Dakota interval. PUH to 600'. Plug #2 with 36 sxs Class B cement from 600' to 400' to cover Gallup top. TOH with tubing, drill collars and 6-1/4" bit. SI well and SDFD.

3-3-99 Safety Meeting. TIH with tubing and tag cement at 480'. Plug #3 with 25 sxs Class B cement with 2% CaCl₂ from 480' to 350'. TOH and WOC. TIH with 15 joints tubing, no tag on cement. Attempt to circulate hole to set additional plug, tubing pressured up to 300# after 1-1/2 bbls. TOH and LD 3 joints of tubing. Establish circulation to surface and circulate well clean. Plug #4 with 91 sxs Class B cement from 385' to surface, circulate 1 bbl good cement out 7" casing. RD rig and equipment, move off location. Charlie Perrin with NMOCD on location and approves plugging plan.

3-5-99 Found cement down 8' in 7" casing, fill 7" casing with 5 sxs Class B cement. Weld on P&A marker.

Daily Report

A - PLUS WELL SERVICE

14636

P.O. BOX 1979 • FARMINGTON, NM 87499
505-325-2627 • FAX (505) 325-1211

Rig No 6

Date 3-1-99

Well No. TH313 Mesa #2 Location Sec 3, T27N, R17W Company MUMOLD
TH313 Mesa P/H Project

[illegible]

Fuel & Motor Oil _____ Water Hauled _____

Rental Equipment 7' Elev, Bit Subs, dc Cement Retainers _____

Cementing Plug #1 24/5x5

Wireline

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	Bill Randall	12	96681	
Operator	Sam Stuart	20		8
Helper	Victor Celis			8
Helper	Doug Hearn	141		9 1/2
Helper	Robert Velasquez			8

Daily Report

A - PLUS WELL SERVICE

14637

P.O. BOX 1979 • FARMINGTON, NM 87499
505-325-2627 • FAX (505) 325-1211

Rig No 6

Date 3-2-99

Well No TABLE Mesa #2 Location Sec 3, T27N, R17W Company NMOC D
TABLE Mesa P/A Project

[illegible]

all procedures approved by Charlie Perman w/numex v
on fol.

Fuel & Motor Oil _____ Water Hauled _____

Rental Equipment _____ Cement Retainers _____

Cementing Plug #1 20 SXS Plug #2 36 SXS

Wireline _____

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	Bill Randall	12	96788	
Operator	SAM Stuart	20	26889	13
Helper	Victor Celis			13
Helper	Robert Velasquez			13
Helper	Doug Hearn	#141		14

Date _____

Daily Report

P.O. BOX 1979 • FARMINGTON, NM 87499
505-325-2627 • FAX (505) 325-1211

14638

Rig No 6

Date 3-3-99

Well No. TABAS MESA #2 Location Sec 3, T29N, R17W Company NMOCID
TABAS MESA P/H Project

[illegible]

Att procedures applied by Charlie Perrin
WYMOULD on hoc.

Fuel & Motor Oil _____ Water Hauled _____

Rental Equipment _____ Cement Retainers _____

Cementing Plug #3 25 SXS Plug #4 91 SXS

Wireline _____

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	Bill Randall	12		
Operator	Sam Stuart	20		9
Helper	Victor Celis			9
Helper	Robert Velasquez			9
Helper	Dan Hernandez	141		9