

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-68

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Federal <input type="checkbox"/>
5. State Oil & Gas Lease No.	
Federal	
7. Unit Agreement Name	
Huercano Unit	
8. Farm or Lease Name	
Huercano Unit	
9. Well No.	
220	
10. Field and Pool, or wildcat	
West Kutz Pic. Cliffs	
12. County	
San Juan	

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>								
2. Name of Operator								
El Paso Natural Gas Company								
3. Address of Operator								
PO Box 990, Farmington, NM 87401								
4. Location of Well								
UNIT LETTER	890	FEET FROM THE	North	LINE AND	860	FEET FROM		
THE	West	LINE, SECTION	30	TOWNSHIP	27N	RANGE	10W	N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.)								
5957'GR								

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data									
NOTICE OF INTENTION TO:					SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK	<input type="checkbox"/>	PLUG AND ABANDON	<input checked="" type="checkbox"/>	REMEDIAL WORK	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>		
TEMPORARILY ABANDON	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>	COMMENCE DRILLING OPS.	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input type="checkbox"/>		
PULL OR ALTER CASING	<input type="checkbox"/>	CASING TEST AND CEMENT JCB	<input type="checkbox"/>	OTHER	<input type="checkbox"/>		<input type="checkbox"/>		
OTHER	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		

17. Permits Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 103.

It is proposed to plug and abandon as follows:

Bradenhead squeeze with 25 sks. cement. Displace cement to 120'.

Squeeze Pictured Cliffs perforation with 25 sks. cement down 2 7/8" O.D. casing.
If well goes on vacuum, follow cement with wireline.

Remove wellhead and cement dry hole marker at surface.

Clean up location.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED: Drilling Clerk DATE: Feb. 8, 1974

APPROVED BY: *Emery L. Lewis*

TITLE: SUPERVISOR DIST. #3 DATE: 2-12-74

CONDITIONS OF APPROVAL, IF ANY:

