Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED /
Budget Bureau No. 1004 0135
Expires: March 31 1993

REUE CONTROL OF THE REPORT	
SUNDRY HOTICES AND REPORTS ON WELLS	5. Lease Designation and Serial No.
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.	NMSF - 078390
Use "APPLICATION FOR PERMIT - " for such proposals 99 AUG - 5	2 belf Indian, Allottee or Tribe Name
OF MED	
11 6 10 11 11 11 17 17	
	Unit or CA, Agreement Designation
Type of Well AUG 0 9 1999	
OII GODD DOD	8. Well Name and No.
Name of Operator	Jones A LS 8
AMOCO PRODUCTION COMPANY DISTO 3 Mary Corley	S. API Well No.
. Address and Telephone No.	
P.O. BOX 3092 HOUSTON TX 77253 281-366-4491	30-045-21030
P.O. BOX 3092 HOUSTON, "X. 77253 281-366-4491	10. Field and Pool, or Exploratory Area
Location of Well (Footage, Sec., T., R., M., or Survey Description)	Blanco South Picture Cliffs
	11. County or Parish, State
1850' FNL 1500' FEL Sec. 15 T 28N R 8W UNIT	G
	SAN JUAN NEW MEXICO
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE	E , REPORT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF	ACTION
Abandomment	
Notice of Intent	Change of Plans
Physics 9 art	New Construction
Subsequent Report Casing Repair	Non-Routine Fracturing
Altering Casing	Water Shut-Off
Final Abandonment Notice Other	Conversion to Injection
	/Note: Report regulate of multiple graphston on Wall Completion of December 1

13. Describe Proposed or Completed Operations (Clearly state all perturent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give markers and zones pertinent to this work.)*

ubsurface locations and measured and true vertical depths for all

6/2/99 MIRUSU. NDWH. NUBOP. TOH w/TBG. TIH W/workstring & CIBP, set @ 2350'. Load CSG & pressure test to 500#. Held OK. RU & rur CBL 2350' to surface. RU &TIH W/TBG to CIBP & spot 1st plug from 2350' to 1900' W15 SXS CIs B Neat CMT. PU & spot 2nd plug @1675' - 1300' W/13 SXS CIs B Neat CMT. RU & shoot 2 SQZ holes @ 190' & spot 3rd plug from 190' inside/outside CSG to surface W/50 SXS CIs B Neat CMT. TOH. NDBOP. Cutoff Wellhead & weld on dryhole marker.

6/3/99 17:00 hrs . RDMOSU. Turned surface location over to environmental group for restoration.

. I hereby certify that the foregoing in Scholar Correct Signed	Title	Sr. Business Analyst	Date 08-03-1999
is space for Federal or State office use)			
Approved by Conditions of approval, if any:	Title		Date RECORL

* See Instructions on Reverse

MMOCD

FARMING STATISTED OFFICE