Form 3160-5 (June 1990)

representations as to any matter within its jurisdiction.

UNITED STATES PARTMENT OF THE INTERIOR

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

BUREAU OF LAND	MANAGEMENT	Expires: March 31, 1993
SUNDRY NOTICES AND	REPORTS ON WELLS deepen or reentry to a different reservoir.	5. Lesse Designation and Serial No. SF-080112 6. If Indian, Allottee or Tribe Name
Use "APPLICATION FOR PERI	MIT - " for such proposals	7. If Unit or CA, Agreement Designation
Type of Well		8, Well Name and No.
Oil Gas Other Name of Operator	Attention: WAYNE BRANAM, RM 1220	RIDDLE F LS #10 8. API Well No.
Amoco Production Company Address and Telephone No.	WATNE BRANAW, TWO TEES	Pictured Cliffs 10. Field and Pool, or Exploratory Area
P.O. Box 800, Denver, Colorado 80201		3004521144
Location of Well (Footage, Sec., T., R., M., or Survey Description)	17 7 00N B 0M	11. County or Parish, State
110 01 02	c. 17 T 28N R 8W	SAN JUAN New Mexico
. CHECK APPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTICE	REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACT	ION
Notice of Intent Subsequent Report Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water te: Report results of multiple completion on Well Completion or
Describe Proposed or Completed Operations (Clearly state all pertine subsurface locations and measured and true vertical depths for all r	ent details, and give pertinent dates, including estimated date of	ompletion Report and Log form.) starting any proposed work . If well is directionally drilled, give
AMOCO PROPOSES TO PLUG AND ABAND	ON THIS WELL PER THE ATTACHED PRO	CEDURE.
	OLL COM. DI DIST. 3	St. Juli 20 Atti: 39 070 Firmington, NM
Signed Alagora		SS ANALYST Date 06-16-1994
This space for Federal or State office use)		
Approved by Conditions of approval, if any:	Title	Date D
Title 18 U.S.C. Section 1001, makes it a crime for any person knowing	gly and willfully to make to any department or agency of the Ut	nited States any false, ficticious, or fraudulent statements or

PXA Procedures Riddle F LS #10

- 1. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
- 2. RIH with 1 1/4" workstring and cement retainer, set retainer at 2060'. Test casing integrity to 500#. Squeeze perfs at 2110' to 2170' with 27.48 cuft cement. Pull out of retainer and spot cement plug to surface. (18.23 cuft cement)
- 3. NDBOP. Cut off casing and wellhead. Install PXA marker according to BlM or State requirements.
- 4. Turn over to John Schwartz for reclamation.
- 5. Rehabilitate location according to BLM or State requirements.

Location — 17M— 28N— 8W

SINGLE PC

Orig.Completion — 4/73

Last File Update — 1/89 by DDM

