Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPRO	OVED
Budget Bureau No.	1004-0135
Expires: March	31, 1993

5. Leace Decomposion and Serial No.

'MM'	 		

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals	6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation
1. Type of Well Oil Gas Well Well Well Cober	Bengalado #1
2. Name of Operator Jerome P. McHugh 3. Address and Telephone No.	°3°0°-0°45°-21186
650 S. Cherry St., Ste 1225, Denver, CO 80222 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	10. Field and Pool, or Exploratory Area WAW Picture Cliff 11. County or Parish, State
1850'FNL 1850'FWL, Sec. 36, T27N, R13W	San Juan, NM
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPOI	RI, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION	
Notice of Inten D) E G E V E Abandonment Recompletion Subsequent Reput SEP 2 6 1991 Final Abandonment Notice CON DIV. Abandonment Casing Repair Altering Casing Other	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Consection or Resport and Log (orm.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

It is proposed to change this well to long term shut-in status.

A well has been drilled to produce the Fruitland Coal in this spacing unit, so this well cannot be completed in the Fruitland Coal.

This well has the potential for production in the Pictured Cliffs in zones at 1116'- 1120' and 1134'- 1140'. Present economics do not justify recompletion work.

It is requested this well be placed on long term shut-in status for the following reasons:

1. The well is currently unable to buck line pressure.

2. The well is unable to produce in paying quantities under current market conditions.

3. The well has additional reserves and has the potential to produce again if market conditions change so recompletion can be justified.

OFD 01 1002

CHIS APPROVA	LEXPIRES SEPUL 1334
_	APPENDING
14. I hereby cerufy that the pregoing is true and correct Signed Title	Date Sept 1991
(This space for Federal or State office use) Approved by Title	SEP 2 1 1991
Conditions of approval, if any:	AREA MANAGER
Tide 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully or representations as to any matter within its jurisdiction.	to make to any department or agency of the United Space any Paise. Tientidus of France left statements