

6 BLM

1 File

UNITED STATES

DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE\*  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

SF 080238

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Gee Gee

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR ARMA

Sec. 31, T27N, R12W, NMPM

12. COUNTY OR PARISH

San Juan

13. STATE

NM

### SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

**RECEIVED**

SEP 25 1985

BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA

1. OIL WELL  GAS WELL  OTHER P & A

2. NAME OF OPERATOR  
DUGAN PRODUCTION CORP.

3. ADDRESS OF OPERATOR  
P O Box 208, Farmington, NM 87499

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\* See also space 17 below.)  
At surface  
1850' FNL - 1850' FEL

14. PERMIT NO.  
15. ELEVATIONS (Show whether DF, ST, GR, etc.)  
5853' GL

#### 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON\*

SHOOTING OR ACIDIZING

ABANDONMENT\*

REPAIR WELL

CHANGE PLANS

(Other) \_\_\_\_\_

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

This well was pulged and abandoned as follows:

- 1) Squeezed existing perfs with 10 sacks cement leaving 100' cement above perfs.
- 2) Backed off 2-7/8" casing as low as possible and filled hole from bottom of casing to surface. *Backed off 1 string*
- 3) Installed permanent dry hole monument.
- 4) Filled all pits.
- 5) Cleaned well location of all equipment, pipe, junk and trash.
- 6) Accomplished surface restoration.
- 7) Cut off tie-downs.

Approved as to plugging of the well bore.  
Liability under bond is retained until  
surface restoration is completed.

**RECEIVED**  
SEP 30 1985  
OIL CON. DIV.  
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED Sherman E. Dugan TITLE Geologist

DATE 9-20-85

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

DATE [Signature]

\*See Instructions on Reverse Side