ABANDON*

CHANGE PLANS

SHOOTING OR ACIDIZING

Form approved.

ABANDON MENT*

Form 9- May 1		Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO. NOO-C-4-20-2976 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	Navajo
	L X GAS OTHER AME OF OPERATOR Northwest Pipeline Corporation	8. FARM OR LEASE NAME Barbara Kay
3. ADI	P.O. Box 90 Farmington, New Mexico 87401	9. WELL NO.
Sec	ocation of Well. (Report location clearly and in accordance with any State requirements.* we also space 17 below.) t surface	10. FIELD AND POOL, OR WILDCAT Wildcat
	900' FNL & 2225' FEL	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 19, T27N, R19W
14. PE	ERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5762 GR	12. COUNTY OF PARISH 13. STATE San Juan N.M.
16.	Check Appropriate Box To Indicate Nature of Notice, Report, or O	other Data
	NOTICE OF INTENTION TO:	ENT REPORT OF:
	TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF PRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT	REPAIRING WELL ALTERING CASING

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

7-8-76 The location and access road was seeded with a mixture as stipulated by the Bureau of Indian Affairs.



SIGNED D.H. Marroncelli	TITLE Production Engineer	7-27-76
(This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE

SHOOT OR ACIDIZE

REPAIR WELL