Form 9-331 (May 4963)

UNITED STATES SUBMIT IN TRIPLICATE* Other instructions on reverse side Form approved. Budget Bureau No. 42-R1424.

9-89-9ND-57

4

GEOLOGICAL SURVEY			9-89-9ND-57
SUNDRY (Do not use this form f	Navajo Jribe 7. CNIT AGREGMENT NAME		
OIL V GAS	of UCB		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	OTHER		S. FARM OR LEASE NAME
John J. Staver dba Saguaro Oil Company 3. Aldress of Operator			Staver Jable Mesa 9. WELL NO.
P. O. Box 51, Farmington, New Mexico 87401 1. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface			7 10. FIELD AND POOL, OR WILDCAT Jable Mesa Dakota
NW NE: 2142 F S	`		11. SEC., T., E., M., OR BLE. AND SURVEY OR ARDA
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, CR, etc.)			Sec. 3. J27N. RI7W 12. COUNTY OF PARISH 13. STATE
Approved 3/9/76	5324 G	•	San Juan No Mo
1.1	• • •	dicate Nature of Notice, Report, o	V
	OF INTENTION TO:		SEQUENT REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER CASING MULTIPLE COMPLETE	WATER SHUT-OFF FRACTURE TREATMENT	REPAIRING WELL ALTERING CASING
SHOOT OR ACIDIZE REPAIR WELL	ABANDON* CHANGE PLANS	SHOOTING OR ACIDIZING (Other)	ABANDONMENT*
(Other)			ults of multiple completion on Well impletion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPI proposed work. If well i nent to this work.) *	EFFED OPERATIONS (Clearly State at its directionally drilled, give subsul	il pertinent details, and give pertinent da rface locations and measured and true ve	ites, including estimated date of starting any rticul depths for all markers and zone s perti-
March 28, 1976,			
Plugs spotted th	rough 2 3/8" drill p	pipe as directed:	
1100 1-1 4631	4 3/4" hole	30 sacks	an girls
440 ⁷ - 700 ⁷	6 3/4" hole	45 sacks	•
02- 102	6 3/4" hole.	5 sacks	
Dry hole marker	not required. Pits	filled and location nest	ored.
			TO BE SEED OF THE REAL
18. I hereby certis that the so	regaing is true and lowest		
SIGNED SIGNED		TE Handgek	DATE 7/6/76
(This spec for Federal or	State office use)		
APPROVED BY CONDITIONS OF APPROV		LE	DATE