UNITED STATES

UNITED STATES	5. LEASE බණ් වී දිස් වි
DEPARTMENT OF THE INTERIOR	9-89-9ND-57 3 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7
GEOLOGICAL SURVEY	6. IF INDIAN, AND THE OR TRIBE NAME Navajo Jacke
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas cher	Staver Jable Mesa
well well unother 2. NAME OF OPERATOR	9. WELL NO. 6.7. 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
John F. Staven dba Saguaro Oil Company	10. FIELD OR WILDCAT NAME
3 ADDRESS OF OPERATOR	Jable Mesa Dakota
P. O. Box 51, Farmington, New Mexico 874	DA1. SEC., T., R., M. OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	Sec. 3. 322H, RETWARD
AT SURFACE:	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	San Juan N. M.
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	Approved 2/4/76
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	7370
TEST WATER SHUT-OFF	
FRACTURE TREAT	그는 그는 그는 학생들이 살아왔다.
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form '9-330.) - 1 4 4 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
CHANGE ZONES	
ABANDON*	
(other)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertiner	irectionally drilled, give subsurface locations and it to this work.)*
Propose to: Pull 52" casing and set following	plugs 1100° = 1359°.
Also 400' - 700' and 0' - 10'. All plugged the	rough 2 3/8" drill pipes
Approximation 1.	150
	一点 人類報告 医肾髓
Subsurface Safety Valve: Manu. and Type	Set @ Fit.
18. I hereby certify that the foregoing is true and correct	
I'Al les-	MIE 10-4-
SIGNED TITLE	WCE VED
(This space for Federal or State off	ice use)