Form	9-331
(May	1063

16.

UNITED STATES UNITED STATES SUBMIT IN TRIPLICATE DEPARTMENT OF THE INTERIOR (Other instructions on reverse side)

GEOLOGICAL SURVEY

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

SF-077874

SUNDRY N	IOTICES	AND	REPORTS	ON	WELLS
----------	---------	-----	---------	----	-------

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

,	(Do not use this form for propo Use "APPLIC.	sals to drill or to deepen or plug back to a different reservoir. ATION FOR PERMIT—" for such proposals.)			
1. OIL WE'.I	CAS WELL X OTHER		7. UNIT AGREEMENT N	AME	
2. NAMI	E OF OPERATOR		8. FARM OR LEASE NA	ME	
So	outhland Royalty Con	pany	Hanks		
	ESS OF OPERATOR		9. WELL NO.		
Р.	O. Drawer 570, Far	mington, New Mexico	#24		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface			10. FIELD AND POOL, OR WILDCAT Undesignated Chacra		
67	'0' FNL & 1850' FEL	and the second s	Blanco Mesa 11. sec., t., e., m., or survey or are	BLK. AND	
		<u> </u>	Src, 5, T27N	, R9W	
14. PER3	HT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARIS	H 13. STATE	
		7103' GR	San Juan	Now Morrison	

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO.			ı	BUBSEQUENT REPORT OF:				
ŕ				- 1			٠ -	_
TEST WATER SHUT-OFF		PULL OR ALTER CASING			WATER SHUT-OFF		REPAIRING WELL	
FRACTURE TREAT		MULTIPLE COMPLETE	<u>X</u>		FRACTURE TREATMENT		ALTERING CASING	
SHOOT OR ACIDIZE		ABANDON*			SHOOTING OR ACIDIZING	L	ABANDONMENT*	
REPAIR WELL		CHANGE PLANS		1	(Other)			
(Other)					(Note: Report rest Completion or Reco	ults o mple	of multive completion on Well tion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Propose to:

- 1. Perforate and frac Chacra zone from 4261'-4273'.
- Set Baker Model "F" packer at 4400'. 2.
- Run 1-1/2" IJ tubing to 5600' with locator seal assembly landed in Model "F" packer and blast joints across Chacra perforated zone.
- Run 1-1/4" IJ tubing to 3230' with 1000' of 1" IJ tailpipe. Total string to be landed at 4230'.

Nipple up dual wellhead.



18. I hereby certify that the toregoing is true and correct SIGNED	TITLE District Engineer	DATE October 19, 1978
(This space for Federal or State office use)		
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE

*See Instructions on Reverse Side

MOCC