----1 1 110 Budget Bureau No. 1004-0135 Form 3:60-5 UNITED STATES SUBMIT IN TRIPLICATE. Expires August 31, 1985 (November 1983) DEPARTMENT OF THE INTERIOR (Other Instructions on re-(Formerly 9-331) 5. LEASE DESIGNATION AND SERIAL NO. BUREAU OF LAND MANAGEMENT NM 33040 6. IF INDIAN, ALLOTTER OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.) 7. UNIT AGREEMENT NAME WELL WELL P&A OTHER 2. NAME OF OPERATOR S. FARM OR LEASE NAME DUGAN PRODUCTION CORP. Faith 3. ADDRESS OF OPERATOR 9. WBLL HO. P O Box 208, Farmington, NM 87499 LOCATION OF WELL (Report location clearly and in accordance with any State requirements See also space 17 below.)
At surface 10. FIELD AND POOL, OR WILDCAT **WAW Pictured Cliffs JAN 29 1987** 790' FSL - 2240' FWL 11. SEC., T., B., M., OR BLK. AND SURVEY OR ARMA **BUREAU OF LAND MANAGEMENT** Sec. 18, T27N, R13W, NMPM FARMINGTON RESOURCE AREA 14. PERMIT NO. 12. COUNTY OR PARISH 13. STATE

6065' GR

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.) *

ABANDON*

CHANGE PLANS

(Other)

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

WATER SHUT-OFF

PRACTURE TREATMENT

San Juan

REPAIRING WELL

ALTERING CASING

SUBSEQUENT REPORT OF:

NM

This well was plugged and abandoned on 12-8-86 as follows:

PULL OR ALTER CASING

MULTIPLE COMPLETE

- 1. Filled 2-7/8" OD, 6.4#, CW-55, 10R, NEUE tubing for casing from P.B.T.D. to surface with 39 sx (46 cf) class "B" neat cement, displacing with water.
- 2. Filled all pits.

NOTICE OF INTENTION TO:

16.

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

- 3. Cleaned well location of all equipment, pipe, junk and trash.
- 4. Cut off tie-downs.

 \mbox{Will} install permanent dry hole monument and restore surface location when weather permits.

Approved as to plugging of the well bore.

Liability under bond is retained until
surface restoration is completed.

	···		APPROVED
SIGNED Neuman S. Dugan	TITLE	Geologist	1-22-87
(This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE _	OIL CON: DIV	FEB 02 1987
*Se	e Instructio	ons on Reverse Side	FARMINGTON RESOURCE AREA