	_					,
NO. OF COPIES RECEIVED						,
DISTRIBUTION	NEW MI	NEW MEXICO OIL CONSERVATION COMMISSION REQUEST FOR ALLOWABLE			Form C	104
SANTA FE /]					-104 edes Old C-104 and C
FILE		AND Effective 1-1-6:				
U.S.G.S.	AUTHORIZATI	ON TO TRA	ANSPORT OIL AND	NATUDAL	CAS	
LAND OFFICE	AUTHORIZATI	1011 10 110	AND ON FOIL AND	INA I UKAL I	GAS	
OIL	-					
TRANSPORTER GAS					484 86	al
	-				AP1 30	-045-23579
PRORATION OFFICE						
Operator WTT	LIAM C. RUSSE	T.T.				
	HILL C. RODDI					
Address					222	
	fth Avenue	New	York, New Y		0022	
Reason(s) for filing (Check proper box			Other (Pleas	e explain;		
New Well	Change in Transpor	ter of:				
Recompletion	011	Dry Go	ıs L			
Change in Ownership	Casinghead Gas	Conder	r.sate			
change of ownership give name nd address of previous owner	. DAGE					
DESCRIPTION OF WELL AND	Well No. Pool Nam	ne. Including F	ormation	Kind of Leas	se	Lease No
Hammond		go Chac		State, Federa	al or Fee Fed.	NM-03603-
	- JZ Lu1	- GO GIIGO		Ctate, today		2
Location						
		_				
Unit Letter O ; 10	14 Feet From The S	South Lir	ne and1980	Feet From	The East	
Unit Letter 0 ; 10	114 Feet From The S	South Lir	ne and1980	Feet From	The East	
0.5	ewnship 27 N	Range 8	3 W , NMPN	, San	Juan	County form is to be sent)
Line of Section 25 To DESIGNATION OF TRANSPOR Name of Authorized Transporter of Co Name of Authorized Transporter of Co El Paso Natural G	tenship 27 N TER OF OIL AND NA Or Condensate Talinghead Gas or Dr Gas Company	Range 8	NMPN	to which appro to which appro 990 Fa	Juan	form is to be sent)
Line of Section 25 To DESIGNATION OF TRANSPOR Name of Authorized Transporter of Co El Paso Natural G	ternship 27 N TER OF OIL AND NA or Condensate Talinghead Gas or Dr Gas Company	Range 8	Address (Give address Address (Give address P. O. Box	to which appro to which appro 990 Fa	Juan oved copy of this formington,	form is to be sent)
Line of Section 25 To DESIGNATION OF TRANSPOR Name of Authorized Transporter of Co Name of Authorized Transporter of Co El Paso Natural Go If well produces oil or liquids, give location of tanks.	TER OF OIL AND NATE OF CONDENSATE asinghed Gas or Dr Gas Company Unit Sec. Two	Range 8 ATURAL GA y Gas X . Ege.	Address (Give address Address (Give address P. O. Box Is gas actually connect No	to which appro to which appro 990 Fa	Juan oved copy of this formington,	form is to be sent)
Line of Section 25 To DESIGNATION OF TRANSPOR Name of Authorized Transporter of Co El Paso Natural G If well produces oil or liquids, give location of tanks. If this production is commingled w	TER OF OIL AND NATE OF CONDENSATE asinghed Gas or Dr Gas Company Unit Sec. Two	Range 8 ATURAL GA y Gas X . Ege.	Address (Give address Address (Give address P. O. Box Is gas actually connect No	to which appro to which appro 990 Fa	Juan oved copy of this formington,	form is to be sent)
Line of Section 25 To DESIGNATION OF TRANSPOR Name of Authorized Transporter of Co Name of Authorized Transporter of Co El Paso Natural Go If well produces oil or liquids, give location of tanks.	TER OF OIL AND NATE OF CONDENSATE Satisfied Gas or Dr Gas Company Unit Sec. Two	Range 8 ATURAL GA y Gas X p. Ege.	Address (Give address Address (Give address P. O. Box Is gas actually connect No	to which approto which appro	Juan oved copy of this poved copy of this prington, nen	form is to be sent) form is to be sent) N. M.
Line of Section 25 To DESIGNATION OF TRANSPOR Name of Authorized Transporter of Co El Paso Natural Co If well produces oil or liquids, give location of tanks. If this production is commingled we COMPLETION DATA	transpector of Condensate or C	Range 8 ATURAL GA y Gas X . Ege. ease or pool, Gas Well	Address (Give address Address (Give address P. O. Box Is gas actually connect No give commingling orde	to which appro to which appro 990 Fa	Juan oved copy of this poved copy of this prington, nen	form is to be sent)
Line of Section 25 To DESIGNATION OF TRANSPOR Name of Authorized Transporter of Co El Paso Natural G If well produces oil or liquids, give location of tanks. If this production is commingled w	transpector of the state of the	Range 8 ATURAL GA y Gas X p. Ree. Gas Well X	Address (Give address Address (Give address P. O. Box Is gas actually connect No give commingling orde New Well Workover	to which approto which appro	Juan oved copy of this formington, nen Flug Back St	form is to be sent) form is to be sent) N. M.
Line of Section 25 To DESIGNATION OF TRANSPOR Name of Authorized Transporter of Co El Paso Natural Co If well produces oil or liquids, give location of tanks. If this production is commingled we COMPLETION DATA	transpector of the state of the	Range 8 ATURAL GA y Gas X p. Ree. Gas Well X	Address (Give address Address (Give address P. O. Box Is gas actually connect No give commingling orde New Well Workover X Total Depth	to which approto which appro	Juan oved copy of this formington, nen Flug Back So	form is to be sent) N. M. ame Res'v. Diff. Res
DESIGNATION OF TRANSPOR Name of Authorized Transporter of Ca El Paso Natural G If well produces oil or liquids, give location of tanks. If this production is commingled w COMPLETION DATA Designate Type of Completi	tranship 27 N TER OF OIL AND NA or Condensate Transhead Gas or Dr Gas Company Unit Sec. Two ith that from any other 16 ion — (X) Date Compl. Ready to P 11-15-79	y Gas X Page. Page. Page. Page. Page. ATURAL GA Y Gas X	Address (Give address Address (Give address P. O. Box Is gas actually connect No give commingling orde New Well Workover X Total Depth 3300	to which approto which appro	Juan oved copy of this formington, nen Flug Back S. P.B.T.D.	form is to be sent) form is to be sent) N. M.
DESIGNATION OF TRANSPOR Name of Authorized Transporter of Co El Paso Natural G If well produces oil or liquids, qive location of tanks. If this production is commingled w COMPLETION DATA Designate Type of Completi	transpector of the state of the	y Gas X Page. Page. Page. Page. Page. ATURAL GA Y Gas X	Address (Give address Address (Give address P. O. Box Is gas actually connect No give commingling orde New Well Workover X Total Depth 3300 Top Oil/Gas Pay	to which approto which appro	Juan oved copy of this formington, nen Flug Back So	form is to be sent) N. M. ame Res'v. Diff. Res
DESIGNATION OF TRANSPOR Name of Authorized Transporter of Ca El Paso Natural G If well produces oil or liquids, give location of tanks. If this production is commingled w COMPLETION DATA Designate Type of Completi Date Spudded 10-30-79	tranship 27 N TER OF OIL AND NA or Condensate Transhead Gas or Dr Gas Company Unit Sec. Two ith that from any other 16 ion — (X) Date Compl. Ready to P 11-15-79	y Gas X Page. Page. Page. Page. Page. ATURAL GA Y Gas X	Address (Give address Address (Give address P. O. Box Is gas actually connect No give commingling orde New Well Workover X Total Depth 3300	to which approto which appro	Juan oved copy of this formington, nen Flug Back S. P.B.T.D.	form is to be sent) N. M. ame Res'v. Diff. Res
DESIGNATION OF TRANSPOR Name of Authorized Transporter of Ca El Paso Natural G If well produces oil or liquids, give location of tanks. If this production is commingled w COMPLETION DATA Designate Type of Completi Date Spudded 10-30-79 Elevations (DF, RKB, RT, GR, etc.,	tranship 27 N TER OF OIL AND NA or Condensate Takinghead Gas or Dr Gas Company Unit Sec. Two ith that from any other 10 ith that from any other 10 Date Compl. Ready to P 11-15-79 Name of Producing Form	y Gas X Page. Page. Page. Page. Page. ATURAL GA Y Gas X	Address (Give address Address (Give address P. O. Box Is gas actually connect No give commingling orde New Well Workover X Total Depth 3300 Top Oil/Gas Pay	to which approto which appro	Juan oved copy of this formington, hen Flug Back So P.B.T.D. 32 Tubing Depth	form is to be sent) N. M. ame Resty. Diff. Res
Line of Section 25 To DESIGNATION OF TRANSPOR Name of Authorized Transporter of Co Rel Paso Natural Go If well produces oil or liquids, give location of tanks. If this production is commingled well production is commingled well production bata Designate Type of Completion Spudded 10-30-79 Elevations (DF, RKB, RT, GR, etc., GR 5973 Perforations	TER OF OIL AND NA or Condensate asinghead Gas or Dr Gas Company Unit Sec. Twr ith that from any other la on - (X) Date Compl. Ready to P 11-15-79 Name of Producing Form Chacra	Range 8 ATURAL GA y Gas X E. Ree. Gas Well X Prod.	Address (Give address Address (Give address P. O. Box Is gas actually connect No give commingling orde New Well Workover X Total Depth 3300 Top Oil/Gas Pay 3104	to which approto which appro	Juan oved copy of this formington, hen Flug Back Sc P.B.T.D. 3220 Depth Casing Sc	form is to be sent) form is to be sent) N. M. ame Res'v. Diff. Res
DESIGNATION OF TRANSPOR Name of Authorized Transporter of Co El Paso Natural G If well produces oil or liquids, give location of tanks. If this production is commingled we COMPLETION DATA Designate Type of Completi Date Spudded 10-30-79 Elevations (DF, RKB, RT, GR, etc., GR 5973	TER OF OIL AND NA or Condensate asinghead Gas or Dr Gas Company Unit Sec. Twr th that from any other la on - (X) Date Compl. Ready to P 11-15-79 Name of Producing Form Chacra	Range 8 ATURAL GA y Gas X F. Rge. Gas Well X Prod.	Address (Give address Address (Give address P. O. Box Is gas actually connect No give commingling orde New Well Workover X Total Depth 3300 Top Oil/Gas Pay 3104 per/ft	to which appro to which appro 990 Fa ed? Wh r number:	Juan oved copy of this formington, nen Flug Back So F.B.T.D. 32 Tubing Depth 3220	form is to be sent) form is to be sent) N. M. ame Res'v. Diff. Res
DESIGNATION OF TRANSPOR Name of Authorized Transporter of Co E1 Paso Natural G If well produces oil or liquids, quive location of tanks. If this production is commingled w COMPLETION DATA Designate Type of Completi Date Spudded 10-30-79 Elevations (DF, RKB, RT, GR, etc., GR 5973 Perforations 3104-3116	transpector of the complete of	Pange 8 ATURAL GA y Gas X p. Eqe. Gas Well X Prod. Indian CASING, ANI	Address (Give address Address (Give address P. O. Box Is gas actually connect No give commingling orde New Well Workover X Total Depth 3300 Top Oil/Gas Pay 3104 per/ft D CEMENTING RECOR	to which appro- to which appro- 990 Fa ed? Wh r number: Deepen	Juan oved copy of this formington, hen Flug Back Si P.B.T.D. Tubing Depth 3220 Depth Casing Si 3300	form is to be sent) N. M. Ame Resiv. Diff. Res
Designate Type of Completi Date Spudded 10-30-79 Elevations (DF, RKE, RT, GR, etc., GR 5973 Perforations Designate Type 104-3116 HOLE SIZE	tranship 27 N TER OF OIL AND NA or Condensate Tasinghead Gas or Dr Gas Company Unit Sec. Twr ith that from any other le ion - (X) Date Compl. Ready to P 11-15-79 Name of Producing Form Chacra 5, 3238-3248 TUBING, CASING & TUBI	Pange 8 ATURAL GA y Gas X p. Eqe. Gas Well X Prod. Indian CASING, ANI	Address (Give address Address (Give address P. O. Box Is gas actually connect No give commingling orde New Well Workover X Total Depth 3300 Top Oil/Gas Pay 3104 per/ft D CEMENTING RECORD	to which appro- to which appro- 990 Fa ed? Wh r number: Deepen	Juan oved copy of this formington, nen Flug Back Si P.B.T.D. 32 Tubing Depth 3220 Depth Casing Si 3300	form is to be sent) N. M. American Resty. Diff. Res
DESIGNATION OF TRANSPOR Name of Authorized Transporter of Co E1 Paso Natural G If well produces oil or liquids, quive location of tanks. If this production is commingled w COMPLETION DATA Designate Type of Completi Date Spudded 10-30-79 Elevations (DF, RKB, RT, GR, etc., GR 5973 Perforations 3104-3116	tranship 27 N TER OF OIL AND NA or Condensate Takinghead Gas or Dr Gas Company Unit Sec. Two ith that from any other 16 ion - (X) Date Compl. Ready to P 11-15-79 Name of Producing Form Chacra 5, 3238-3248 TUBING, CASING & TUBI 8 5/8	Pange 8 ATURAL GA y Gas X p. Eqe. Gas Well X Prod. Indian CASING, ANI	Address (Give address Address (Give address P. O. Box Is gas actually connect No give commingling orde New Well Workover X Total Depth 3300 Top Oil/Gas Pay 3104 per/ft D CEMENTING RECORD DEPTHS 238	to which appro- to which appro- 990 Fa ed? Wh r number: Deepen	Juan oved copy of this formington, nen Flug Back Si P.B.T.D. 32 Tubing Depth 3220 Depth Casing Si 3300 SACI	form is to be sent) N. M. Ame Res'v. Diff. Res 271 Choose
Designate Type of Completi Date Spudded 10-30-79 Elevations (DF, RKB, RT, GR, etc., GR 5973 HOLE SIZE 124 DESIGNATION OF TRANSPOR TRANSPOR TRANSPOR TRANSPOR TRANSPOR TRANSPOR TRANSPOR TRANSPOR TRANSPOR TO TO TO TO TO TO TO TO TO	tranship 27 N TER OF OIL AND NA or Condensate Tasinghead Gas or Dr Gas Company Unit Sec. Twr ith that from any other le ion - (X) Date Compl. Ready to P 11-15-79 Name of Producing Form Chacra 5, 3238-3248 TUBING, CASING & TUBI	Pange 8 ATURAL GA y Gas X p. Eqe. Gas Well X Prod. Indian CASING, ANI	Address (Give address Address (Give address P. O. Box Is gas actually connect No give commingling orde New Well Workover X Total Depth 3300 Top Off/Gas Pay 3104 Per/ft CEMENTING RECORD DEPTHS 238 3300	to which appro- to which appro- 990 Fa ed? Wh r number: Deepen	Juan oved copy of this formington, nen Flug Back Si P.B.T.D. 32 Tubing Depth 3220 Depth Casing Si 3300	form is to be sent) N. M. Ame Res'v. Diff. Res 271 Choose
Designate Type of Completi Date Spudded 10-30-79 Elevations (DF, RKE, RT, GR, etc., GR 5973 Perforations Designate Type 104-3116 HOLE SIZE	tranship 27 N TER OF OIL AND NA or Condensate Takinghead Gas or Dr Gas Company Unit Sec. Two ith that from any other 16 ion - (X) Date Compl. Ready to P 11-15-79 Name of Producing Form Chacra 5, 3238-3248 TUBING, CASING & TUBI 8 5/8	Pange 8 ATURAL GA y Gas X p. Eqe. Gas Well X Prod. Indian CASING, ANI	Address (Give address Address (Give address P. O. Box Is gas actually connect No give commingling orde New Well Workover X Total Depth 3300 Top Oil/Gas Pay 3104 per/ft D CEMENTING RECORD DEPTHS 238	to which appro- to which appro- 990 Fa ed? Wh r number: Deepen	Juan oved copy of this formington, nen Flug Back Si P.B.T.D. 32 Tubing Depth 3220 Depth Casing Si 3300 SACI	form is to be sent) N. M. Ame Res'v. Diff. Res 271 Choose
Designate Type of Completi Date Spudded 10-30-79 Elevations (DF, RKB, RT, GR, etc., GR 5973 HOLE SIZE 124 DESIGNATION OF TRANSPOR TRANSPOR TRANSPOR TRANSPOR TRANSPOR TRANSPOR TRANSPOR TRANSPOR TRANSPOR TO TO TO TO TO TO TO TO TO	TER OF OIL AND NATIONAL COMMENTS OF CONDENSATE OF DIL AND NATIONAL COMMENTS OF	Pange 8 ATURAL GA y Gas X p. Eqe. Gas Well X Prod. Indian CASING, ANI	Address (Give address Address (Give address P. O. Box Is gas actually connect No give commingling orde New Well Workover X Total Depth 3300 Top Off/Gas Pay 3104 Per/ft CEMENTING RECORD DEPTHS 238 3300	to which appro- to which appro- 990 Fa ed? Wh r number: Deepen	Juan oved copy of this formington, hen Flug Back S P.B.T.D. 3220 Depth Casing S 3300 SACI	form is to be sent) N. M. Ame Res'v. Diff. Res 271 Choose
Designate Type of Completi Date Spudded 10-30-79 Elevations (DF, RKE, RT, GR, etc., GR 5973 Perforations 125 HOLE SIZE 124 7 7/8	TER OF OIL AND NATION OF Condensate or Dr. Condensate or Condensate or Dr. Condensate or Condensat	Range 8 ATURAL GA y Gas X E. Ree. Case or pool, Gas Well X Prod. CASING, ANI NG SIZE	Address (Give address Address (Give address P. O. Box Is gas actually connect No give commingling orde New Well Workover X Total Depth 3300 Top Oil/Gas Pay 3104 Per/ft DEPTHS 238 3300 3220	to which approto which approto which approto 990 Fa ed? Which approto Which approto Which approto Which approto Poespen Poes	Juan oved copy of this formington, nen Flug Back St. P.B.T.D. 32 Tubing Depth 3220 Depth Casing St. 3300 SAC: 250 1100	form is to be sent) form is to be sent) N. M. ame Res'v. Diff. Res 271 Shoe Company of the sent
Designate Type of Completi Date Spudded 10-30-79 Elevations (DF, RKE, RT, GR, etc., GR 5973 Perforations HOLE SIZE 124 7 7/8 TEST DATA AND REQUEST F	TER OF OIL AND NATION OF Condensate of Conde	Range 8 ATURAL GA y Gas X p. Rege. ease or pool, Gas Well X Prod. CASING, ANI NG SIZE	Address (Give address Address (Give address P. O. Box Is gas actually connect No give commingling orde New Well Workover X Total Depth 3300 Top Oil/Gas Pay 3104 Per/ft DEPTHS 238 3300 3220 after recovery of total volutions	to which approto which appropriate which appropriate with appropriate with a proto which appropriate with a proto wit	Juan oved copy of this formington, hen Flug Back Si P.B.T.D. Tubing Depth 3220 Depth Casing Si 3300 SAC: 250 1100	form is to be sent) form is to be sent) N. M. ame Res'v. Diff. Res 271 Shoe Company of the sent
Designate Type of Completi Date Spudded 10-30-79 Elevations (DF, RKE, RT, GR, etc., GR 5973 Perforations 124 7 7/8 TEST DATA AND REQUEST FOIL, WELL.	TER OF OIL AND NATE OF CONDENSATE Tasinghead Gas or Dr. Tasinghead	Range 8 ATURAL GA y Gas X p. Rege. ease or pool, Gas Well X Prod. CASING, ANI NG SIZE	Address (Give address Address (Give address P. O. BOX Is gas actually connect No give commingling orde New Well Workover X Total Depth 3300 Top Oil/Gas Pay 3104 Per/ft DEPTHS 238 3300 3220 after recovery of total volumenth or be for full 24 hour	to which approto which approto which approto 990 Fa ed? Which approto Which approto Which approto Which approto Poeepen Deepen Deepen Which approto Deepen Which approto Deepen Which approto Which	Juan oved copy of this formington, hen Flug Back S. P.B.T.D. Tubing Depth 3220 Depth Casing S. 3300 SAC: 250 1100	form is to be sent) form is to be sent) N. M. ame Res'v. Diff. Res 271 Shoe Company of the sent
Designate Type of Completi Date Spudded 10-30-79 Elevations (DF, RKE, RT, GR, etc., GR 5973 Perforations HOLE SIZE 124 7 7/8 TEST DATA AND REQUEST F	TER OF OIL AND NATION OF Condensate of Conde	Range 8 ATURAL GA y Gas X p. Rege. ease or pool, Gas Well X Prod. CASING, ANI NG SIZE	Address (Give address Address (Give address P. O. Box Is gas actually connect No give commingling orde New Well Workover X Total Depth 3300 Top Oil/Gas Pay 3104 Per/ft DEPTHS 238 3300 3220 after recovery of total volutions	to which approto which approto which approto 990 Fa ed? Which approto Which approto Which approto Which approto Poeepen Deepen Deepen Which approto Deepen Which approto Deepen Which approto Which	Juan oved copy of this formington, hen Flug Back S. P.B.T.D. Tubing Depth 3220 Depth Casing S. 3300 SAC: 250 1100	form is to be sent) form is to be sent) N. M. ame Res'v. Diff. Res 271 Shoe Company of the sent
Designate Type of Completi Date Spudded 10-30-79 Elevations (DF, RKE, RT, GR, etc., GR 5973 Perforations 124 7 7/8 TEST DATA AND REQUEST FOIL, WELL.	TER OF OIL AND NATE or Condensate or Condens	Range 8 ATURAL GA y Gas X p. Rege. ease or pool, Gas Well X Prod. CASING, ANI NG SIZE	Address (Give address Address (Give address P. O. Box Is gas actually connect No give commingling orde New Well Workover X Total Depth 3300 Top Oil/Gas Pay 3104 Per/ft D CEMENTING RECORD DEPTHS 238 3300 3220 Ifter recovery of total volument or be for full 24 hour Producing Method (Flori	to which approto which approto which approto 990 Fa ed? Which approto Which approto Which approto Which approto Poeepen Deepen Deepen Which approto Deepen Which approto Deepen Which approto Which	Juan oved copy of this formed copy of this formington, nen Flug Back Signature Signa	form is to be sent) N. M. Ame Res'v. Diff. Res 271 Common to be sent) N. M.
Designate Type of Completi Date Spudded 10-30-79 Elevations (DF, RKE, RT, GR, etc., GR 5973 Perforations 124 7 7/8 TEST DATA AND REQUEST FOIL, WELL.	TER OF OIL AND NATE OF CONDENSATE Tasinghead Gas or Dr. Tasinghead	Range 8 ATURAL GA y Gas X p. Rege. ease or pool, Gas Well X Prod. CASING, ANI NG SIZE	Address (Give address Address (Give address P. O. BOX Is gas actually connect No give commingling orde New Well Workover X Total Depth 3300 Top Oil/Gas Pay 3104 Per/ft DEPTHS 238 3300 3220 after recovery of total volumenth or be for full 24 hour	to which approto which approto which approto 990 Fa ed? Which approto Which approto Which approto Which approto Poeepen Deepen Deepen Which approto Deepen Which approto Deepen Which approto Which	Juan oved copy of this formington, hen Flug Back S. P.B.T.D. Tubing Depth 3220 Depth Casing S. 3300 SAC: 250 1100	form is to be sent) form is to be sent) N. M. ame Res'v. Diff. Res 271 Shoe Company of the sent
Designate Type of Completions (DF, RKB, RT, GR, etc., GR 5973 Perforations Authorized Type of Completion Data Spudded 10-30-79 Elevations (DF, RKB, RT, GR, etc., GR 5973 Perforations Authorized Transporter of Completion Data Spudded 10-30-79 Elevations (DF, RKB, RT, GR, etc., GR 5973 Perforations 3104-3116 HOLE SIZE 124 7 7/8 TEST DATA AND REQUEST FOIL WELL Date First New Cil Run To Tanks	TER OF OIL AND NATE or Condensate or Condens	Range 8 ATURAL GA y Gas X p. Rege. ease or pool, Gas Well X Prod. CASING, ANI NG SIZE	Address (Give address Address (Give address P. O. Box Is gas actually connect No give commingling orde New Well Workover X Total Depth 3300 Top Oil/Gas Pay 3104 Per/ft Depths 238 3300 3220 Infer recovery of total volumenth or be for full 24 hour Producing Method (Flow Casing Pressure	to which approto which approto which approto 990 Fa ed? Which approto Which approto Which approto Which approto Poeepen Deepen Deepen Which approto Deepen Which approto Deepen Which approto Which	Juan oved copy of this formington, hen Flug Back S. F.B.T.D. 3220 Tubing Depth 3220 Depth Casing S. 3300 SACI 250 1100 I and must be equal ift, etc.) for size	form is to be sent) form is to be sent) N. M. The sent of the s
Designate Type of Completions (DF, RKB, RT, GR, etc., GR 5973 Perforations Authorized Type of Completion Data Spudded 10-30-79 Elevations (DF, RKB, RT, GR, etc., GR 5973 Perforations Authorized Transporter of Completion Data Spudded 10-30-79 Elevations (DF, RKB, RT, GR, etc., GR 5973 Perforations 3104-3116 HOLE SIZE 124 7 7/8 TEST DATA AND REQUEST FOIL WELL Date First New Cil Run To Tanks	TER OF OIL AND NATE or Condensate or Condens	Range 8 ATURAL GA y Gas X p. Rege. ease or pool, Gas Well X Prod. CASING, ANI NG SIZE	Address (Give address Address (Give address P. O. Box Is gas actually connect No give commingling orde New Well Workover X Total Depth 3300 Top Oil/Gas Pay 3104 Per/ft D CEMENTING RECORD DEPTHS 238 3300 3220 Ifter recovery of total volument or be for full 24 hour Producing Method (Flori	to which approto which approto which approto 990 Fa ed? Which approto Which approto Which approto Which approto Poeepen Deepen Deepen Which approto Deepen Which approto Deepen Which approto Which	Juan oved copy of this formed copy of this formington, nen Flug Back Signature Signa	form is to be sent) form is to be sent) N. M. The sent of the s

GAS WELL
Actual Prod. Test-MCF/D Gravity of Condensate Bbls. Condensate/MMCF Length of Test 1652 3 hrs Casing Pressure (Shut-in) Choke Size Testing Method (pitot, back pr.) Tubing Pressure (Shut-in) 3/4 1012 back pr. 1012

VI. CERTIFICATE OF COMPLIANCE

Ш

I hereby certify that the rules and regulations of the Oil Conservation Commission have been complied with and that the information given above is true and complete to the best of my knowledge and belief.

Millian C. (Rusself
(Signature)
Operator
(Title)
12-20-79

(Date)

OIL CONSERVATION COMMISSION

APPROVED	JAN L	, 19
BYOrigina	al Signae by AR 4000	11/4/FZ
TITLE		

This form is to be filed in compliance with RULE 1104.

If this is a request for allowable for a newly drilled or deepened well, this form must be accompanied by a tabulation of the deviation tests taken on the well in accordance with RULE 111.

All sections of this form must be filled out completely for allowable on new and recompleted wells.

Fill out only Sections I. II. III, and VI for changes of owner, well name or number, or transporter, or other such change of condition.

Separate Forms C-104 must be filed for each pool in multiply completed wells.