UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

		5.	Lease Number NM-013861
. Type of Well GAS	\$1 × 100		If Indian, All. or Tribe Name
		7.	Unit Agreement Name
. Name of Operator			
RESOURCES OIL & GAS COMPANY			
Address & Phone No. of Cherater		8.	Well Name & Number Grambling A #1A
. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505)	326-9700	9.	
. Location of Well, Footage, Sec., T, R, M		10.	Field and Pool
1850'FNL, 1850'FWL, Sec.21, T-28-N, R-8-W,	NMPM		Blanco Mesaverde
F		11.	County and State San Juan Co, NM
Casing R Final Abandonment Altering	Back Non-Ro epair Water Casing Conver Tubing repair	Shut o	££
3. Describe Proposed or Completed Operation	ns		
9-5-00 MIRU. SDON. 9-6-00 ND WH. NU BOP. TIH, tag up @ 47 4772'. Attempt to establish @ 9-7-00 Blow well & CO. SDON.		tbg.	TIH w/3 7/8" mill to
9-5-00 MIRU. SDON. 9-6-00 ND WH. NU BOP. TIH, tag up @ 47 4772'. Attempt to establish	circ. SDON TOOH. TIH w/147	jts 2	
9-5-00 MIRU. SDON. 9-6-00 ND WH. NU BOP. TIH, tag up @ 47 4772'. Attempt to establish @ 9-7-00 Blow well & CO. SDON. 9-8-00 Establish circ. Circ hole clean	circ. SDON TOOH. TIH w/147	jts 2	
9-5-00 MIRU. SDON. 9-6-00 ND WH. NU BOP. TIH, tag up @ 47 4772'. Attempt to establish @ 9-7-00 Blow well & CO. SDON. 9-8-00 Establish circ. Circ hole clean	circ. SDON TOOH. TIH w/147	jts 2	
9-5-00 MIRU. SDON. 9-6-00 ND WH. NU BOP. TIH, tag up @ 47 4772'. Attempt to establish @ 9-7-00 Blow well & CO. SDON. 9-8-00 Establish circ. Circ hole clean	circ. SDON TOOH. TIH w/147	jts 2	
9-5-00 MIRU. SDON. 9-6-00 ND WH. NU BOP. TIH, tag up @ 47 4772'. Attempt to establish @ 9-7-00 Blow well & CO. SDON. 9-8-00 Establish circ. Circ hole clean	circ. SDON TOOH. TIH w/147	jts 2	
9-5-00 MIRU. SDON. 9-6-00 ND WH. NU BOP. TIH, tag up @ 47 4772'. Attempt to establish @ 9-7-00 Blow well & CO. SDON. 9-8-00 Establish circ. Circ hole clean landed @ 4681'. ND BOP. NU W.	circ. SDON TOOH. TIH w/147 H. RD. Rig release	jts 2	
9-5-00 MIRU. SDON. 9-6-00 ND WH. NU BOP. TIH, tag up @ 47 4772'. Attempt to establish @ 9-7-00 Blow well & CO. SDON. 9-8-00 Establish circ. Circ hole clean landed @ 4681'. ND BOP. NU W	circ. SDON TOOH. TIH w/147 H. RD. Rig release	jts 2	
9-5-00 MIRU. SDON. 9-6-00 ND WH. NU BOP. TIH, tag up @ 47 4772'. Attempt to establish g-7-00 Blow well & CO. SDON. 9-8-00 Establish circ. Circ hole clean landed @ 4681'. ND BOP. NU W.	circ. SDON TOOH. TIH w/147 H. RD. Rig release	jts 2 d.	
9-5-00 MIRU. SDON. 9-6-00 ND WH. NU BOP. TIH, tag up @ 47 4772'. Attempt to establish g-7-00 Blow well & CO. SDON. 9-8-00 Establish circ. Circ hole clean landed @ 4681'. ND BOP. NU W.	true and correct.	jts 2 d.	3/8" 4.7# J-55 EUE tb