

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT --" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well: ☐ OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION, INC.

3. Address and Telephone No. 3300 H. Butler Suite 100, Farmington NM 87401 325-4397

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Unit Letter G : 1850 Feet From The NORTH Line and 1850 Feet From The
EAST Line Section 07 Township 27N Range 13W

5. Lease Designation and Serial No.
NM 14973

6. If Indian, Alottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and Number
DOME FEDERAL 07-27-13
3

9. API Well No.
3004524047

10. Field and Pool, Exploratory Area
BASIN FRUITLAND COAL (GAS)

11. County or Parish, State
SAN JUAN, NM

12. Check Appropriate Box(s) To Indicate Nature of Notice, Report, or Other Data

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Attaching Casing
☐ OTHER: _____

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

TEXACO E. & P., Inc. PROPOSES TO PLUG AND ABANDON THE SUBJECT WELL:

PLEASE SEE ATTACHED PLUGGING PROCEDURE AND WELLBORE DIAGRAMS.

RECEIVED
DEC 12 1994
OIL CON. DIV.
DIST. 3

070 PM 12/12/94

51 DEC -5 PM 12:08

RECEIVED

14. I hereby certify that the foregoing is true and correct

SIGNATURE Ted A. Tipton TITLE Operations Unit Manager DATE 12/1/94

TYPE OR PRINT NAME Ted A. Tipton

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

DEC 01 1994

DISTRICT MANAGER

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

DOMESTIC FEDERAL 7-27-13 #3
PLUG AND ABANDONMENT PROCEDURE

1. MURUSU. Notify BLM to witness.
2. TCOH w/ TBG. TIH w/ 4.5" CMT RET. Set RET @ 1250'.
3. Plug well as discussed w/ BLM. Load hole and establish injection rate into Frt. perforations. Pump 9 sx (1.86 bbl) class "G" CMT through RET.
4. String out of RET and spot 56 sx (18.3 bbl) POZ CMT to 100'.
5. POOH w/ TBG. Spot w/ Class "G" CMT 100' to surface (\approx 9 sx or 1.6 bbl). POOH.
6. Remove all surface equipment. Reclaim location. Erect P&A marker.



DOMe FEDERAL 7-27-13 No. 3 **Current Completion**

WELL:

Dome Federal 7-27-13 #3
 API No. 30-045-240470001

LOCATION:

SW/4 NE/4
 Sec. 7 T27N R13W
 San Juan County, New Mexico

ELEVATION: 6013' GL

FORMATION TOPS:


Farmington - 560'
 Fruitland Coal - 990'
 Pictured Cliffs - 1330'

FRUITLAND COAL PERFS:

1298-1305, 1312-1330

PICTURED CLIFFS PERFS:

1343-1346, 1352-1355





DOME FEDERAL 7-27-13 No. 3

Proposed Plug and Abandonment

WELL:

Dome Federal 7-27-13 #3
API No. 30-045-240470001

LOCATION:

SW/4 NE/4
Sec. 7 T27N R13W
San Juan County, New Mexico

ELEVATION: 6013' GL

FORMATION TOPS:

Farmington - 560'
Fruitland Coal - 990'
Pictured Cliffs - 1330'

FRUITLAND COAL PERFS:
1298-1305, 1312-1330

PICTURED CLIFFS PERFS:
1343-1346, 1352-1355

