

F

30-045-28254

09-24-90

F. Loc. 1190/S; 790/W Elev. 6050 GL Spd. _____ Comp. _____ TD _____ PB _____
 Cu. ft. _____ Cu. ft. _____
 Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. T. _____ @ _____
 Csg. Perf. _____ Prod. Stim. _____

T Gas
R
A
N
S

BO/D _____ Grav. _____ 1st Del. Gas _____
 I.P. _____ MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ 1st Del. Oil _____

TOPS		NIID	Well Log	TEST DATA						
Ojo Alamo		C-103	Plat X	Schd.	PC	Q	PW	PD	D	Ref.No.
Kirtland		C-104	Electric Log							
Fruitland			C-122							
Pictured Cliffs		Ditr	Dfa							
Chacra		Datr	Dac							
Cliff House		Acres S/320								
Menefee										
Point Lookout										
Mancos										
Gallup										
Greenhorn										
Dakota										
Entrado										

P
o
o

BasinFrCoalCo.SJ S 13 T 27N R 11W U M Oper.Bonneville Fuels Corp.Lse.Fullerton Fed. 13 No. 14

Fullerton Federal 13 #14

M-13-27N-11W

BONNEVILLE FUELS CORP.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Farmington Resource Area
1235 Laplata Highway
Farmington, New Mexico 87401



IN REPLY REFER TO:

SF-078094 et al. (WC)
3162.3-1.0 (019)

NOV. 14 1991

Bonneville Fuels Corporation
1600 Broadway, Suite 1110
Denver, Co. 80202

RECEIVED
NOV 15 1991
OIL CON. DIV.
DIST. 3

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

1. No. 14-14 Fullerton Federal, Sec. 14, T. 27 N., R. 11 W., San Juan County, New Mexico, lease SF-078094.
2. No. 36-23 Scott E Federal, Sec. 36, T. 27 N., R. 11 W., San Juan County, New Mexico, lease SF-078089.
3. No. 24-23 Scott E Federal, Sec. 24, T. 27 N., R. 11 W., San Juan County, New Mexico, lease SF-078089.
4. No. 13-14 Fullerton Federal, Sec. 13, T. 27 N., R. 11 W., San Juan County, New Mexico, lease SF-078094.
5. No. 24-12 Scott E Federal, Sec. 24, T. 27 N., R. 11 W., San Juan County, New Mexico, lease SF-078089.

As discussed with Doris Moly of your company on, October 16, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within the approved period of time.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

John L. Keller
Chief, Branch of Mineral Resources

5 Enclosures

cc:
New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410

ABANDONED LOCATION