Casing S@w Csg.Perf.	. Cu. ft. Sx. In	·	6610 GL w_	Cu. ft. Sx. Pr Prod. Stirr			.w	Cu. ft.	·	°8 @	1 Gas
PBO/D After_	Hrs. SICI)p	SI After	Grav		1st De	el. <u>Gas</u>				R A N
Ojo Alamo	NITD	X	Well Log		TEST DAT	1st De	el. Oil				_
Kirtland	C-103		Plat				,				
	C-104		Electric Log	X	Schd.	PC	9	PW	PD	D	Ref.No
Fruitland			C-122		 						
Pictured Cliffs	Ditr	-L	Dfa								
Chacra	Datr		 								
Cliff House			Dac								
Menefee											
Point Lookout											
Mancos											·
Gallup											
Greenhorn	-										
Dakota											
intrada	1							+			
	1		Acre	es N/320							

BasinFrCoalCo. SJ \$ 24 127N R 08W UG Oper. Maralex Resources Inclo Marron W.N. Fed. C. No. 10

	المنافعة المراجعة	·		-
=				
			1	



United States Department of the Interior

BUREAU OF LAND MANAGEMENT Farmington Resource Area 1235 Laplata Highway Farmington, New Mexico 87401



SF-078478 (WC) 3162.3-1.0 (019)

JAN. 🔁 🐈

Maralex Resources, Inc. 518 17th Street, Suite 1030 Denver, CO 80202 JAN2 8 1992
OIL CON. DIV

Gentlemen:

Enclosed is your Application for Permit to Drill (APD) well No. 10 Marron W. N. Federal Com., Sec. 24, T. 27 N, R. 8 W, San Juan County, New Mexico, lease SF-078478. As discussed with Jenifer Ritcher of your company on January 17, 1992, the subject APD is rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ Ken Townsend

FOR John L. Keller Chief, Branch of Mineral Resources

1 Enclosure

cc: New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410

ABANDONED LOC

Marron W.N. Federal Com. #10 G-24-27N-08W

MARALEX RESOURCES, INC.