Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED			
Budget Bureau No.	1004 - 0135		
Expires: March	31 1993		

		Expires:	March	31, 199	93	
5.	Lease	Designat	ion and	Seria	No.	

SHINDRY	NOTICES	AND	REPORTS	ON WELLS
CONDIN	14011020	7110		OII II LLLO

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FO	R PERMIT—" for such proposals	
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
Type of Well Well Gas Well Other 2. Name of Operator		8. Well Name and No. Scott Federal 23-42
3. Address and Telephone No.	els Corporation	9. API Well No. 3004528516
1660 Lincoln, Suite 1800, Denver, CO 80264 (303) 863-1555 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		10. Field and Pool, or Exploratory Area W. KutzPicturedCliffs
1620' FNL, 330' FEL Sec 23H T27N R11W		II. County or Parish, State San Juan, NM
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPOR	RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	

Notice of Intent	Abandonment	Change of Plans
	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other	Dispose Water
		(Note: Report results of multiple completion on Well
		Completion or Recompletion Report and Log form 1

Bonneville Fuels Corporation requests permission to recomplete the above referenced well in the Fruitland Coal.

	1	
14. I hereby sertify that the loregoing is true and confect Signed	Operations Manager	AS AMENDED
(This space for Federal or State office use) Approved by Conditions of approval, if any:	Title	SEP 1 4 1992 AREA MANAGER

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

See attached for recompletion procedure.

^{13.} Describe Proposed or Completed Operations (Clearly state all pertinent defails, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Scott Federal #23-42 KB 6148, GL 6136, PBTD 1899KB 5½ J55 15.5# csg @ 1943KB Perfs 1836-48, 24½ "holes

Fruitland Coal Recompletion

- 1. Kill well, ND Wellhead, NU BOPs
- 2. Tag Bottom and TOH w/tbg Tallying out
- 3. PU 4 1/2" bit and scrapper, TIH w/ 2 7/8" work string
- 4. Clean out to bottom of csg
- 5. TOH w/ tbg, bit and scrapper
- 6. TIH w/ tbg and Arrow type 32 packer
- 7. Set packer @1810KB
- 8. Squeeze open hole w/ ±25 sxs class B CMT and additives, displace to packer.
- 9. SI 24hrs.
- 10. TOH w/ tbg and packer
- 11. PU 4 5/8" bit, scrapper and TIH w/ tbg, clean out to 1836KB
- 12. Set CIBP @ 1834KB
- 13. Pressure up CSG to 500 psi and test squeeze
- 14. TOH w/ tbg and bit
- 15. Perforate w/ csg gun 1818-25 and 1743-47 4spf
- 16. Breakdown perfs w/ 500 gal 15% HCL and flush with 2% KCL water
- 17. Frac w/ 23,000 gal 70 Q N_2 foam and 40,000 lbs 20/40 sand.
- 18. Circulate sand out to CIBP
- 19. TOH w/ packer and tbg
- 20. Set retriveable bridge plug @ 1700KB
- 21. Perforate from 1652-56 and 1631-35 4spf
- 22. Breakdown perfs w/ 500 gals 15% HCL and flush with 2% KCL
- 23. Frac w/ 22,000 gal 70 Q N_2 foam and 36,000 lbs 20/40 sand.
- 24. TIH w/ tbg and retrieving head, and circulate sand out to RBP
- 25. TOH w/ tbg and RBP
- 26. TIH w/ 2 3/8" production the and hang off @1730KB
- 27. Swab well on, and test
- 28. Hookup compressor, pipeline and place on line