Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

				
	Expires:	March	31,	1993
•				

	SF-080382-A		
SUNDRY NOTICES AND RE	6. If Indian, Allottes or Tribe Name		
Do not use this form for proposals to drill or to d			
Use "APPLICATION FOR PERMIT	Navajo Nation NIIP		
SUBMIT IN TRIF	7. If Unit or CA, Agreement Designation		
1. Type of Well			
Oil Gas Well Other	8. Well Name and No. Schwerdtfeger "28" #1		
2. Name of Operator Marathon Oil Company	9. API Well No.		
3. Address and Telephone No.		30-045-29014	
P.O. Box 552 Midland, Tx. 79702	915-682-1626	10. Field and Pool, or Exploratory Area	
	VIO 002 1130	Basin Fruitland Coel	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) UL "L" 1470' FSL & 1250' FWL	11. County or Parish, State		
Sec 28, T-27-N, R-11-W		··· co, a	
	_	San Juan Co., N M	
12. CHECK APPROPRIATE BOX(s) TO IN	DICATE NATURE OF NOTICE, REPO	ORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTION		
Notice of Intent	Abandonment	Change of Plans	
LI POLICE OF INVAN	Recompletion	New Construction	
Subsequent Report	Plugging Back	Non-Routine Practuring	
E23 Stoephent Nebest	Casing Repair	☐ Water Shot-Off	
Final Ahandonment Notice	Altering Casing	Conversion to Injection	
L. Pink Administrative Police	K Other New Well Completion	Dispose Water	
	22 0000	(Note: Report results of authipte completion on Well	
		Completion or Recompletion Report and Los form.	
13. Describe Proposed or Completed Operations (Clearly state all pertinent de give subsurface locations and measured and true vertical depths for	rall markers and zones pertinent to this work.)* bill as per the history summarized belo		
1_30_94		ressure tested casing to	
1-20-94 MRU PU. RiH with bit and scraper to 2078' PBTD 2500 PSI. Test OK. POOH with work string. Ran	. Circulate hole clean With 2 % KCl. P CCL/CBL/GR. Perfed 1781-85, 1786-	-95, 1818-28 with 4 JSPF. Rin string. Installed Frac valve.	
1-20-94 MRU PU. RIH with bit and scraper to 2078' PBTD 2500 PSI. Test OK. POOH with work string. Ran with Pinpoint Injection Tool. Acidized 1781-1828	. Circulate hole clean With 2 % KCl. P CCL/CBL/GR. Perfed 1781-85, 1786- using PPI tool. POOH with treatment a ality foamed N2 carrying 136,000# sa	string. Installed Frac valve. Ind. Blew back to pit to clean	
1-20-94 MIRU PU. RIH with bit and scraper to 2078' PBTD 2500 PSI. Test OK. POOH with work string. Ran with Pinpoint Injection Tool. Acidized 1781-1828 Fractured 1871-1828 with 60,000 gallons 70 qu	. Circulate hole clean With 2 % KCl. PCL/CBL/GR. Perfed 1781-85, 1786-using PPI tool. POOH with treatment ality foamed N2 carrying 136,000# sa 2 3/8 production string. Seating hip	-95, 1818-28 with 4 JSPT. NET string. Installed Frac valve. nd. Blew back to pit to clean ple @ 1837 KBM. Swabbed well	
1-20-94 MIRU PU. RIH with bit and scraper to 2078' PBTD 2500 PSI. Test OK. POOH with work string. Ran with Pinpoint Injection Tool. Acidized 1781-1828 Fractured 1871-1828 with 60,000 gallons 70 qu	. Circulate hole clean With 2 % KCl. PCL/CBL/GR. Perfed 1781-85, 1786-using PPI tool. POOH with treatment ality foamed N2 carrying 136,000# sa 2 3/8 production string. Seating hip	istring. Installed Frac valve. Ind. Blew back to pit to clean ple @ 1837 KBM. Swabbed wel urned into test separator.	
1-20-94 MIRU PU. RIH with bit and scraper to 2078' PBTD 2500 PSI. Test OK. POOH with work string. Ran with Pinpoint Injection Tool. Acidized 1781-1828 Fractured 1871-1828 with 60,000 gallons 70 qu	. Circulate hole clean With 2 % KCl. PCL/CBL/GR. Perfed 1781-85, 1786-using PPI tool. POOH with treatment ality foamed N2 carrying 136,000# sa 2 3/8 production string. Seating hip	string. Installed Frac valve. Ind. Blew back to pit to clean ple @ 1837 KBM. Swabbed wel urned into test separator.	
1-20-94 MIRU PU. RiH with bit and scraper to 2078' PBTD 2500 PSI. Test OK. POOH with work string. Ran with Pinpoint Injection Tool. Acidized 1781-1828	. Circulate hole clean With 2 % KCl. PCL/CBL/GR. Perfed 1781-85, 1786-using PPI tool. POOH with treatment ality foamed N2 carrying 136,000# sa 2 3/8 production string. Seating hip	string. Installed Frac valve. nd. Blew back to pit to clean ple @ 1837 KBM. Swabbed well urned into test separator.	
1-20-94 MIRU PU. RIH with bit and scraper to 2078' PBTD 2500 PSI. Test OK. POOH with work string. Ran with Pinpoint Injection Tool. Acidized 1781-1828 Fractured 1871-1828 with 60,000 gallons 70 qu	. Circulate hole clean With 2 % KCl. PCCL/CBL/GR. Perfed 1781-85, 1786-using PPI tool. POOH with treatment ality foamed N2 carrying 136,000# sa 2 3/8 production string. Seating nip k to continue clean up. RDMO PU. To	string. Installed Frac valve. Ind. Blew back to pit to clean ple @ 1837 KBM. Swabbed wel urned into test separator.	
1-20-94 MIRU PU. RiH with bit and scraper to 2078' PBTD 2500 PSI. Test OK. POOH with work string. Ran with Pinpoint Injection Tool. Acidized 1781-1828 Fractured 1871-1828 with 60,000 gallons 70 qu	. Circulate hole clean With 2 % KCl. PCCL/CBL/GR. Perfed 1781-85, 1786-using PPI tool. POOH with treatment ality foamed N2 carrying 136,000# sa 2 3/8 production string. Seating nip k to continue clean up. RDMO PU. To	string. Installed Frac valve. nd. Blew back to pit to clean ple @ 1837 KBM. Swabbed well urned into test separator.	
1-20-94 MIRU PU. RiH with bit and scraper to 2078' PBTD 2500 PSI. Test OK. POOH with work string. Ran with Pinpoint Injection Tool. Acidized 1781-1828 Fractured 1871-1828 with 60,000 gallons 70 qu	. Circulate hole clean With 2 % KCl. PCL/CBL/GR. Perfed 1781-85, 1786-using PPI tool. POOH with treatment ality foamed N2 carrying 136,000# sa 2 3/8 production string. Seating hip	string. Installed Frac valve. nd. Blew back to pit to clean ple @ 1837 KBM. Swabbed well urned into test separator.	
1-20-94 MIRU PU. RIH with bit and scraper to 2078' PBTD 2500 PSI. Test OK. POOH with work string. Ran with Pinpoint Injection Tool. Acidized 1781-1828 Fractured 1871-1828 with 60,000 gallons 70 qu	. Circulate hole clean With 2 % KCl. PCCL/CBL/GR. Perfed 1781-85, 1786-using PPI tool. POOH with treatment ality foamed N2 carrying 136,000# sa 2 3/8 production string. Seating nip k to continue clean up. RDMO PU. To	string. Installed Frac valve. Ind. Blew back to pit to clean ple @ 1837 KBM. Swabbed wel urned into test separator. PER BER BER BER BER BER BER BER BER BER B	

14. I hereby certify that the foregoing is true and correct Signed Abundan By R.A. Biernbaum	Title Operations Superintendent	Dets 2-2-94
(This space for Federal or State office use)	Title	Date
Approved by		ACCEPTED FOR RECORD
Tide 18 U.S.C. Section 1001, makes it a crime for any person knowing or representations as to any matter within its jurisdiction.	ly and willfully to make to any department or agency	of the United Seeds of Seed 1894 or Standards same

OIL CON. DIV. dist. 9

*See instruction on Reverse Side

FARMINGTON DISTRICT OFFICE

PLATE T

BY ____