

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF 079319

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL GAS WELL OTHER

7. UNIT AGREEMENT NAME

2. NAME OF OPERATOR

Tenneco Oil Company

8. FARM OR LEASE NAME

Schwerdtfeger "A"

3. ADDRESS OF OPERATOR

P. O. Box 1714, Durango, Colorado 81301

9. WELL NO.

2

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

990 FNL, 990 FWL

10. FIELD AND POOL, OR WILDCAT

Basin Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 31, T-28-N, R-8-W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5887 Gr.

12. COUNTY OR PARISH

13. STATE

San Juan

New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING


ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We propose to plug and abandon well as follows: Rig up pulling unit run tubing open ended, spot open hole plug @ 4881, 100 sx cmt. Pull tubing and spot 25 sack cmt plug at surface. Set dry hole marker and release rig.

4-1/2" casing set @ 6770. Two stage cement w/375 sx and 675 sx. Casing parted @ 4881. Cut off @ 110.56 and pulled 90.06' of 9.5# J-55. Casing free from 3750-600.



18. I hereby certify that the foregoing is true and correct

SIGNED M. K. Wagner
M. K. Wagner

TITLE _____

DATE July 17, 1967

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____