5-USGS (Farmington) 1-Flag-Red	itern (Greave	s) 1-File					
UNITED STATES SUBMIT IN TRIPLICATE (Mi.s. 1863) DEPARTMENT OF THE INTERIOR verse side) GEOLOGICAL SURVEY			re-	Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.			
			1	M-010063			
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)				F INDIAN, ALLOI	TEE OR TRI	BE NAME	
1. OIL GAS V		, , , , , , , , , , , , , , , , , , , ,	7. 0	NIT AGREEMENT	NAME :		
WELL WELL OTHER 2. NAME OF OPERATOR				ABM OR LEASE	NAME -		
Flag-Redfern Oil Compar	ıv		I	ucerne		.	
3. ADDRESS OF OPERATOR				VELL NO			
Box 234, Farmington, NA				1 5 2			
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)				FIELD AND POOL		AT -	
At surface 790' FSL - 1850' FWL			<u> </u>	Undesignated 11. sec., T., B., M., OR BLK. AND			
			ļ	SURVEY OR A		71	
			5	Sec 8, T28	3N, R11	W	
14. PERMIT NO. 15. ELEV	ATIONS (Show whether	• • •	12.	COUNTY OR PAR		ATE	
	5526'	GR	5	an Juan-		NM:	
16. Check Appropriate	Box To Indicate	Nature of Notice, Report, o	r Other	Data 3 3 3			
NOTICE OF INTENTION TO:		SUB	SEQUENT E	EPORT OF	7 1	5 <u>}</u>	
TEST WATER SHUT-OFF PULL OR AL	TER CASING	WATER SHUT-OFF		REPAIRIN	G WELL	Ŧ	
FRACTURE TREAT MULTIPLE (FRACTURE TREATMENT		ALTERIN	CASING		
SHOOT OR ACIDIZE ABANDON*	X	SHOOTING OR ACIDIZING		VRVXDOV	MENT*	<u> </u>	
REPAIR WELL CHANGE PL	ANS	(Other)(Note: Report res	ulte of m	iltinia aoministi	on on Well	الت	
(Other)		Completion or Reco	mpletion	Report and Log	form.)		
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (C proposed work. If well is directionally drillenent to this work.)*	d, give subsurface lo	cations and measured and true ver	tical dep	ths for all-mar	kers_and zo	nes perti-	
nent to this work,			-	distribution of the second		音楽 ら	
			3	dada bud bud	- T	当皇 第	
1. Plan to squeeze perfs	586-616' wit	h 15 cu ft cement (t	op cen	ient 350?)			
2. Spot 10 sx cement in surface			3	nthus I botto Double Walter	cot Bur Stock c	area Treatm	
3. Cut off surface casing	and 2-7/8"	tubing 3' below grou	nđ	to sinago edi sol en en dol) a en monil	tions tions see to		
4. Clean up location				ngor f Lancai O) aili on II ta		भा सम्बद्ध अनुसर्वा	
5. Seed location as directed by Bureau of Land Management.				tomes debt deb debt debt debt	eini bi bi en eini edde en eini eachtag		
				ererry majori mojan surpo-		[]	
				fichta ok. of. Appara ougs i	- 10 to 10 t	41	
	y Pr	<i>\</i>					
	* *		****	(A)	- 교육 분 등 - 통 리 (중	严重	
	. Pad as	A. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.	MAR			₹ <u>₹</u>	
	قر الم	Fr. State of the S			÷ =		
, (•		
		No BRanto			· · · · · · · · · · · · · · · · · · ·	<u> </u>	
18. I hereby certify that the forefoling is true and	correct	Dotroloum Engineer			2 - 25-77		
Thomas A. Dugan	TITLE	Petroleum Engineer		DATE			
(This space for Federal or State office use)						:	
APPROVED BY	TITLE			DATE	·:		
CONDITIONS OF APPROVAL, IF ANY:					1. 1.		