

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other

2. NAME OF OPERATOR
Tenneco Oil Company

3. ADDRESS OF OPERATOR
Box 3249, Englewood, CO 80155

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1750' FNL, 890' FWL "E"
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

☐
☒
☒
☐
☐
☐
☐
☐
☐

5. LEASE
SF-077085

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Omler A

9. WELL NO.
5E

10. FIELD OR WILDCAT NAME
Basin Dakota/Chacra

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Section 25, T28N, R10W

12. COUNTY OR PARISH
San Juan

13. STATE
New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
5802' gr.

(NOTE: Report results of multiple completion or zone change on Form 9-330)

1981
OIL CON. COM.
DIST. 3

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

3/4/81. RIH w/2-3/8" tbg. and pump out plug. Clean out to PBTD @ 6644' w/foam. Killed Dakota w/2% KCL water. Landed tbg. in BOP @ 6265'. POOH w/tbg. Set 7" Baker model D pkr. w/expendable plug on wireline @ 3077'. Dumped 2 sx sand on pkr. and loaded hole w/2% KCL water. Pressure test pkr. to 3000 PSI. Held OK. Perf'd Chacra w/4" csg. gun @ 1 JSPF as follows: 2870-72', 2966-73', 2976-81', 14', 28 holes. RIH w/tbg. and 7" tension pkr. to 2825'.

3/6/81. Established rate: 7½ BPM @ 2500 PSI. Acidized Chacra w/600 gals 15% HCL and 42-1.1 specific gravity balls. RIH w/tbg. and knock balls off perfs. Unloaded hole w/N₂. POOH w/tbg. and pkr. Frac'd Chacra w/80,000 gals 75% quality foamed 2% KCL water and 80,000# 20/40 sand down csg. AIR: 20 BPM, AIP: 1400 PSI, ISIP: 1550 PSI, 15 min SIP: 1300 PSI. Flowed well back thru 1/2" choke. Left flowing.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Carly Matheson TITLE Asst. Div. Adm. Mgr. DATE 3/12/81

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____ DATE _____

NMOCC

MAR 31 1981

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.