Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. LEASE DESIGNATION AND SERIAL NO

		10 to	NM010063
	SUNDRY NOTICES AND REF	PORTS ON WELLS-TO TO PM 1: 1	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Do not use	e this form for proposals to drill or to dee		
DO 1101 030	Use "APPLICATION FOR PERMI		4
			7. IF UNIT OR CA, AGREEMENT DESIGNATION
SUBMIT IN TRIPLICATE		8910073050	
TYPE OF WELL		8. WELL NAME AND NO.	
OIL WELL GAS WELL OTHER :		LUCERNE #1E	
NAME OF OPERATOR		9. API WELL NO.	
	CONOCO INC.		30-045-24333
	ADDRESS AND TELEPHONE NO.		10. FIELD AND POOL, OR EXPLORATORY AREA
10 DEST	A DR., SUITE 100W, MIDLAND,	TX 79705-4500 (915)686-5424	BASIN DAKOTA / SAN JUAN DRI
LOCATION OF WELL (Footage, Sec., T., R., M., or Survey Description) 1100' FSL AND 1540' FEL, SEC. 08, T27N, R11W, UNIT LTR 'O'			11. COUNTY OR PARISH, STATE
		SAN JUAN, NM	
	CHECK APPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTICE,	REPORT, OR OTHER DATA
TYPE OF SUBMISSION		TYPE OF ACTION	
		Abandonment	Change of Plans
<u></u> П	Notice of Intent	Recompletion	New Construction
Subsequent Report		Plugging Back Non-Routine Fracturing	
Final Abandonment Notice		Casing Repair Water Shut-Off	
		Altering Casing	Conversion to Injection
		Other: PERF, ACIDIZE, INSTALL	
			(Note: Report results of multiple completion on Well Completion Recompletion Report and Log Form.)
 Describe Productionally 	oposed or Completed Operations (Clearly state all p drilled, give subsurface locations and measured an	pertinent details, and give pertinent dates, including esti d true vertical depths for all markers and zones pertine	nt to this work.)
Describe Produced directionally	drilled, give subsurface locations and measured an MIRU. POOH TBG. PERF DAKO 6122', 6132' - 6135', 6154' - 6158'	d true vertical depths for all markers and zones pertine TA WITH 3-1/8" HSC PERF GUN 1 JS ', 6160' - 6163', 6188' - 6190', 6197' - 6 ICI WITH 100 1.3 SG BALL SEALERS	nt to this work.) SPF, .38 HOLES, 6048' - 6055', 6102' - 6201', AND 6206' - 6208'. ACIDIZE S. RIH WITH MULESHOE COLLAR, SN
directionally	drilled, give subsurface locations and measured an MIRU. POOH TBG. PERF DAKO 6122', 6132' - 6135', 6154' - 6158' PERFS WITH 1350 GALS. 15% HAT 193 JTS 2-3/8" TBG, SN AT 6	d true vertical depths for all markers and zones pertine TA WITH 3-1/8" HSC PERF GUN 1 JS ', 6160' - 6163', 6188' - 6190', 6197' - 6 ICI WITH 100 1.3 SG BALL SEALERS	nt to this work.) SPF, .38 HOLES, 6048' - 6055', 6102' - 6201', AND 6206' - 6208'. ACIDIZE S. RIH WITH MULESHOE COLLAR, SN
directionally	drilled, give subsurface locations and measured an MIRU. POOH TBG. PERF DAKO 6122', 6132' - 6135', 6154' - 6158' PERFS WITH 1350 GALS. 15% H	d true vertical depths for all markers and zones pertine TA WITH 3-1/8" HSC PERF GUN 1 JS ', 6160' - 6163', 6188' - 6190', 6197' - 6 ICI WITH 100 1.3 SG BALL SEALERS	nt to this work.) SPF, .38 HOLES, 6048' - 6055', 6102' - 6201', AND 6206' - 6208'. ACIDIZE 6. RIH WITH MULESHOE COLLAR, SN
directionally	drilled, give subsurface locations and measured an MIRU. POOH TBG. PERF DAKO 6122', 6132' - 6135', 6154' - 6158' PERFS WITH 1350 GALS. 15% HAT 193 JTS 2-3/8" TBG, SN AT 6	d true vertical depths for all markers and zones pertine TA WITH 3-1/8" HSC PERF GUN 1 JS ', 6160' - 6163', 6188' - 6190', 6197' - 6 ICI WITH 100 1.3 SG BALL SEALERS	nt to this work.) SPF, .38 HOLES, 6048' - 6055', 6102' - 6201', AND 6206' - 6208'. ACIDIZE S. RIH WITH MULESHOE COLLAR, SN
directionally	drilled, give subsurface locations and measured an MIRU. POOH TBG. PERF DAKO 6122', 6132' - 6135', 6154' - 6158' PERFS WITH 1350 GALS. 15% HAT 193 JTS 2-3/8" TBG, SN AT 6	d true vertical depths for all markers and zones pertine TA WITH 3-1/8" HSC PERF GUN 1 JS ', 6160' - 6163', 6188' - 6190', 6197' - 6 ICI WITH 100 1.3 SG BALL SEALERS	nt to this work.) SPF, .38 HOLES, 6048' - 6055', 6102' - 6201', AND 6206' - 6208'. ACIDIZE 6. RIH WITH MULESHOE COLLAR, SN
directionally 1-6-97 1-10-97	drilled, give subsurface locations and measured an MIRU. POOH TBG. PERF DAKO 6122', 6132' - 6135', 6154' - 6158' PERFS WITH 1350 GALS. 15% HAT 193 JTS 2-3/8" TBG, SN AT 6	d true vertical depths for all markers and zones pertine TA WITH 3-1/8" HSC PERF GUN 1 JS ', 6160' - 6163', 6188' - 6190', 6197' - 6 ICI WITH 100 1.3 SG BALL SEALERS	nt to this work.) SPF, .38 HOLES, 6048' - 6055', 6102' - 6201', AND 6206' - 6208'. ACIDIZE 6. RIH WITH MULESHOE COLLAR, SN
directionally 1-6-97 1-10-97	drilled, give subsurface locations and measured an MIRU. POOH TBG. PERF DAKO 6122', 6132' - 6135', 6154' - 6158' PERFS WITH 1350 GALS. 15% HAT 193 JTS 2-3/8" TBG, SN AT 6 RDMO.	d true vertical depths for all markers and zones pertine TA WITH 3-1/8" HSC PERF GUN 1 JS ', 6160' - 6163', 6188' - 6190', 6197' - 6 ICI WITH 100 1.3 SG BALL SEALERS	nt to this work.) SPF, .38 HOLES, 6048' - 6055', 6102' - 5201', AND 6206' - 6208'. ACIDIZE 5. RIH WITH MULESHOE COLLAR, SN
directionally 1-6-97 1-10-97	drilled, give subsurface locations and measured an MIRU. POOH TBG. PERF DAKO 6122', 6132' - 6135', 6154' - 6158' PERFS WITH 1350 GALS. 15% HAT 193 JTS 2-3/8" TBG, SN AT 6 RDMO.	d true vertical depths for all markers and zones pertine TA WITH 3-1/8" HSC PERF GUN 1 JS ', 6160' - 6163', 6188' - 6190', 6197' - 6 ICI WITH 100 1.3 SG BALL SEALERS 105'.	nt to this work.) SPF, .38 HOLES, 6048' - 6055', 6102' - 6201', AND 6206' - 6208'. ACIDIZE S. RIH WITH MULESHOE COLLAR, SN
directionally 1-6-97 1-10-97 I hereby certain SIGNED	drilled, give subsurface locations and measured an MIRU. POOH TBG. PERF DAKO 6122', 6132' - 6135', 6154' - 6158' PERFS WITH 1350 GALS. 15% HAT 193 JTS 2-3/8" TBG, SN AT 6 RDMO.	d true vertical depths for all markers and zones pertine TA WITH 3-1/8" HSC PERF GUN 1 JS 1, 6160' - 6163', 6188' - 6190', 6197' - 6 ICI WITH 100 1.3 SG BALL SEALERS 105'. DEBRA BEMENDER	nt to this work.) SPF, .38 HOLES, 6048' - 6055', 6102' - 6201', AND 6206' - 6208'. ACIDIZE S. RIH WITH MULESHOE COLLAR, SN
directionally 1-6-97 1-10-97 I hereby certain SIGNED	drilled, give subsurface locations and measured an MIRU. POOH TBG. PERF DAKO 6122', 6132' - 6135', 6154' - 6158' PERFS WITH 1350 GALS. 15% HAT 193 JTS 2-3/8" TBG, SN AT 6 RDMO.	d true vertical depths for all markers and zones pertine TA WITH 3-1/8" HSC PERF GUN 1 JS 1, 6160' - 6163', 6188' - 6190', 6197' - 6 ICI WITH 100 1.3 SG BALL SEALERS 105'. DEBRA BEMENDER	RFER OCO INC. DATE 2-6-97
directionally 1-6-97 1-10-97 4. I hereby cer SIGNED (This space	drilled, give subsurface locations and measured an MIRU. POOH TBG. PERF DAKO 6122', 6132' - 6135', 6154' - 6158' PERFS WITH 1350 GALS. 15% HAT 193 JTS 2-3/8" TBG, SN AT 6 RDMO.	d true vertical depths for all markers and zones pertine TA WITH 3-1/8" HSC PERF GUN 1 JS 1, 6160' - 6163', 6188' - 6190', 6197' - 6 ICI WITH 100 1.3 SG BALL SEALERS 105'. DEBRA BEMENDER TITLE AGENT FOR CONC	RFER OCO INC. DATE 2-6-97

* See Instruction on Reverse Side

FEB 1 4 1997

