Form 9-331 Dec. 1973

Form Approved. Budget Bureau No. 42-R1424

## UNITED STATES

UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	Contract #81 # 352
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	Jicarilla Apache
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAMES 6 241.
(Do not use this form for proposals to drill or to deepen or plug back to a different	
reservoir, Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas 🕥	Indian A ুঠিকু টি প্রীটি
well well other	9. WELL NO.
2. NAME OF OPERATOR	#3 \$\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
Northwest Pipeline Corporation	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Choza Mesa Pictured Cliffs
P.O. Box 90, Farmington, N.M. 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA STORY TO SEE THE
below.) AT SURFACE: 1485' FSL & 1080' FWL	Sec 29 T29N R3W
AT TOP PROD. INTERVAL:Same as above	12. COUNTY OR PARISH   13. STATE
AT TOTAL DEPTH: Same as above	14 401 00
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.	30-039-21379 T \$ \$ \$ 15
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	7108' GR 2 6 3 6 6 6
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	1 2 0 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
TEST WATER SHUT-OFF	2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
FRACTURE TREAT	
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9-330.)
MULTIPLE COMPLETE	/ 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
CHANGE ZONES	
(other)	
	3 3 1 3 CON 5 1 3 6 7 7
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details) and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and	
measured and true vertical depths for all markers and zones pertinent to this work.)*	
1. Cleaned out well with $1-1/4$ " tubing	and gas to T.D. So we will be seen and gas to T.D.
<u>.</u>	
2. Set BP at 3850'.	
3. Unloaded well with gas after landing tubing at 3805.  4. Well would not sustain production.  4. Well would not sustain production.	
4. Well would not sustain production.	
	Service of the servic
	- 15 (20 mm )
₹.	
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
Subsurface Safety valve, Mariu, and Type	38 W 3 3 4 3 4 4 5 5 7 6 7 6 7 6 7 6 7 6 7 6 7 6 7 6 7 6
18. I hereby certify that the focegoing is true and correct	
SIGNED TITLE Sr. Prod Engineer DATE July 1, 1980	
(This space for Federal or State office use)	
APPROVED BY TITLE DATE	
CONDITIONS OF APPROVAL, IF ANY:	
NMOCOL SE	

ישטטעואו