Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS o not use this form for proposals to drill or to deepen or reentry to a different rese Use "APPLICATION FOR PERMIT—" for such proposals	
o not use this form for proposals to drill or to deepen or reentry to a different rese	6. If Indian, Allonee or Tribe Name
	7. If Unit or CA. Agreement Designation
SUBMIT IN TRIPLICATE	GALLEGOS CANYON UNIT
pe of Well	8. Well Name and No.
Oil	NO. 49
P PETROLEUM (AMERICAS) INC.	9. API Well No.
ddress and Telephone No.	30-045-07076 10. Field and Pool, or Exploratory Area
O. BOX 977 FARMINGTON, N.M. 87499 (505) 327-1639	BASIN FRUITLAND COAL
ocation of Well (Footage, Sec., T., R., M., or Survey Description)	11. County or Parish, State
0' FNL AND 892' FEL	
/NE SEC.31, T28N, R12W	SAN JUAN, NEW MEXIC
CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE,	REPORT, OR OTHER DATA
TYPE OF A	
TYPE OF SUBMISSION	
Notice of Intent	Change of Plans New Construction
Recompletion	Non-Routine Fracturing
Subsequent Report	Water Shut-Off
Casing Repair	Gion to Injection
Final Abandonment Notice Altering Casing CompLETION HI Other	
	(Note: Report results of multiple completion on We Completion or Recompletion Report and Log form
THE DAILY HISTORY OF THE COMPLETION OPERATIONS FOR IS ATTACHED.	ن ن <u>ن</u>
	20 ALIV
	SO ME
	SO ME
	SO ME
	SO MILES
	SO ALIVE
	SO ME
	SO ME
	SO ALIVE
	CENTED OF AR SOLA NM
	CENTED ON ROOM SOIN NM
1 hereby certify that the foregoing is true and correct MANAGER FIELD O	CENTED ON ROOM SOIN NM
I hereby certify that the forcesoing is true and correct MANAGER FIELD O	CENTED ON ROOM SOIN NM
I hereby certify that the foregoing is true and correct FRED LOWERY Signed	OPS. 02-12-96 ACCEPTED FOR RECOR
I hereby certify that the foregoing is true and correct FRED LOWERY Signed	SELVED AND SILB

GALLEGOS CANYON UNIT NO. 49

11-07-95 SICP 155 PSI. BLEW WELL DOWN. ND WELL HEAD AND NU BOPE.POOH AND LAY DOWN 1 1/4" TBG. GIH W/ BIT & CSG. SCRAPER TO 1297' KB. POOH PU PKR & TIH. SET PKR. @ 1265' AND LOAD HOLE WITH 2% KCL WATER. TEST CSG. TO 500 PSI. OK. RU SWAB AND SWAB WELL DOWN. SWAB TEST WELL FOR 2 HOURS WITH NO GAS TO SURFACE, RECOVERED LESS THAN 1 BBL WTR. RELEASE PHR. & POOH. RU LOGGERS AND RAN A GR/CNL LOG FM: 1293' TO 500'. GIH & SET A CIBP @ 1272' KB. LOAD CSG. WITH 2% KCL WTR. & TESTED CSG. TO 500 PSI. OK. GIH & RAN CBL FROM PBTD TO SURFACE. RD LOGGERS. GIH W/ TBG. AND ROLL HOLE WITH 2% KCL WTR. ND BOPE & NU WELL HEAD.

11-29-95 ND WELL HEAD & NU BOPE. RU PERFORATORS AND PERFORATE THE FRUITLAND COAL FROM 1251' TO 67' W/ 4" HSC LOADED W/ 4 JSPF, 19 GRAM SHOOTING A .50 HOLE, 65 HOLES. NO GAS TO SURFACE. PU PKR ON 2 7/8" TBG. & TIH. SET PKR @ 1166' KB. TESTED TO 500 PSI, OK. SWAB TBG.DRY WITH NO GAS TO SURFACE.

11-30-95 RU DOWELL AND FRACTURE STIMULATE THE FRUITLAND COAL WITH 250 GAL.
15% HCL ACID FOLLOWED WITH 402 BBL OF 30# BORATE X-LINKED GEL AND 40,000# OF
20/40 SAND. MAX. PRESSURE 2300 PSI, AVG. 1950 PSI. MAX. SAND CONC. 6 PPG. AVG.
RATE 25 BPM. ISIP 1070 PSI. SHUT WELL IN TWO HOURS FOR GEL BREAK. SITP 640
PSI. WELL FLOWED BACK ON A 3/8" CHOKE FOR 1.5 HOURS. RECOVERED 50 BBL LOAD
FLUID AND DIED. NO GAS TO SURFACE.

12-01-95 NO PRESSURE ON WELL. RELEASE PKR AND POOH. L.D. TBG. PU 2 3/8' TBG AND TIH. TAG SAND @ 1236' KB. CIRCULATE HOLE CLEAN W/ 2% KCL WTR. TO PBTD. LAND TBG. @ 1269'. GIH W/ INSERT PUMP AND RODS. SPACE OUT AND HANG OFF. SET PUMPING UNIT AND RU.

12-02-95 WELL DID NOT PUMP, POOH WITH RODS & PUMP. PUMP FULL OF FRAC SAND. RERAN PUMP & RODS. PUMP TESTING TO TANK.

12-03-95 PUMP TEST TO TANK FOR 8 DAYS WITH NO GAS TO SURFACE. RECOVERED 164 BBL LOAD FLUID.

CONTINUE TO PUMP TEST WELL FOR 24 DAYS. RECOVERED 203 BBL LOAD FLUID WITH THE GAS RATE INCREASING FROM 54 MCF/D TO 126 MCF/D. SHUT WELL IN FOR BUILD UP. SEVEN DAY SICP 179 PSI.

WELL SHUT IN WOPL