Form 9-331 (May 1963)

UNITED STATES DEPARTMENT OF THE INTERIOR

SUBMIT IN TRIPLICATE*


(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.
LEASE DESIGNATION AND SERIAL NO.

DEPARTMENT OF THE INTERIOR verse side) GEOLOGICAL SURVEY			SF-077968 6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
SUNDRY NOTIC (Do not use this form for proposals Use "APPLICATI	7. UNIT AGREEMENT NAME			
OIL GAS WELL OTHER NAME OF OPERATOR			8. FARM OR LEASE NAME Southeast Cha Cha	
Aztec Oil and Gas Company 3. ADDRESS OF OPERATOR New Movico 87401			9. WELL NO. #7	
P.O. Box 570, Farmington, New Mexico 87401 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)			10. FIELD AND POOL, OR WILDCAT Gallup	
At surface 660 FSL & 1960 FWL Section 8-28n-13w	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 8-28-13W			
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, $6038GR$		12. COUNTY OR PARISH San Juan	New Mex.
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Date SUBSEQUENT REPORT NOTICE OF INTENTION TO:			Other Data UENT REPORT OF:	,
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE A	ULTIPLE COMPLETE BANDON®	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) Temporari (Note: Report result Completion or Recom	ALTERING C ABANDONME Ly Abandoned s of multiple completion pletion Report and Log for	ASINGX

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Moved in. Rigged up. Installed Blow Out Preventer. Pulled Rods and tried to unset Packer. Pulled out of hole. Recovered 17 jts of 2 3/8" tubing. Started in hole with overshot unable to get through bad spot @ 2000'. Pulled out of hole. Ran bit with casing scrapper. Worked through bad spot @ 2000'. Finished going in hole with bit and scrapper to top of Fish. Hung up. Worked loose. Pulled out of hole. Ran overshot. Unable to get over Fish. Tubing that was unable to recover was 5 jts. of 2 3/8 and one-A-1 lockset packer. Laid down rods and tubing. Temporarily Abandoned.



18. I hereby certify that the foregoing is true and correct	TITLE District superintendent	DATE 6-21-74
(This space for Federal or State office use) APPROVED BY	TITLE	DATE