		E INTERIOR (Other Instruction	PLICATE.	Budget Bureau No. 1004-0 Expires August 31, 1985 5. ERABE DESIGNATION AND SERIAL P
	BUREAU OF LAND MA	NAGEMENT	V	SF-078828
(Do not use this form	Y NOTICES AND RE of the proposals to drill of to des "APPLICATION FOR PERMIT	room on minus book to a diff.		S. IF INDIAN, ALLOTTES OR TRIBE NA
I. OIL CAR WELL WELL OTHER 2. NAME OF OPERATOR			7	URIT AGREEMENT NAME
				Gallegos Canyon Ur
Amoco Producti	ion Co		8	. PARM OR LEASE NAME
3. ADDRESS OF OPERATOR			9.	. WRLL NO.
501 Airport Drive, Farmington, N M 87401 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface			10	207
	1000	KECEIVED		Basin Dakota
1282, E.N.T	L x 1980'FEL	MAY 02 1985	11	1. EBC., T., E., M., OR BLK. AND SURVEY OR ARMA
4. PERMIT NO.	BL	TREAU OF LAND MAN-CEMENT		SW/NE Sec14,T28N,R
16. PERMIT NO. 18. BLEVATIONS (SHOPEWAY) DE WERE AREA 5766 RDB			12	2. COUNTY OR PARISH 13. STATE
6.				San Juan NM
v. C	heck Appropriate Box Tail	Indicate Nature of Notice, Repo	ort, or Othe	er Data
	OF INTENTION TO:			REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF		REPAIRING WELL X
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATME	NT	ALTERING CARING
SHOOT OR ACIDIES	ABANDON*	SHOOTING OR ACIDIE	ING	ARANDONMENT®
REPAIR WELL (Other)	CHANGE PLANS	(Other)		naitiple completion on Well
from 1000' to	surface. Found	e unit on 2/16/84. casing leak 18' fro	m surf	ace Cut
from 1000' to	surface. Found	e unit on 2/16/84. casing leak 18' fro replaced. Released	m surf	ace Cut
from 1000' to	surface. Found	casing leak 18' fro	m surf	ace Cut
from 1000' to	surface. Found	casing leak 18' fro	m surf	ace Cut
from 1000' to	surface. Found	casing leak 18' fro	m surf	ace Cut
from 1000' to	surface. Found	casing leak 18' fro	om surf	ace. Cut ig on 2/22/84.
from 1000' to	surface. Found	casing leak 18' fro	om surf	ace. Cut ig on 2/22/84.
from 1000' to	surface. Found	casing leak 18' fro	om surf	ace. Cut ig on 2/22/84.
from 1000' to	surface. Found	casing leak 18' fro	om surf	ace. Cut ig on 2/22/84.
off 1 joint 4-	surface. Found 1/2" casing and rolag is true and correct ned By	casing leak 18' from replaced. Released	om surf d the r	ace. Cut ig on 2/22/84.
off 1 joint 4- Off 1 joint 4- Original Signary B. D. Sh	surface. Found 1/2" casing and rolag is true and correct ned By TITE	casing leak 18' fro	om surf d the r	ace. Cut ig on 2/22/84.
off 1 joint 4-	surface. Found 1/2" casing and rotag is true and correct ned By Titte office use)	casing leak 18' from replaced. Released	om surf the r	ace. Cut ig on 2/22/84.
bereby certify that the fores Ofiginal Signification This space for Federal or Sta	surface. Found 1/2" casing and rotag is true and correct ned By Titte office use)	casing leak 18' from replaced. Released	om surfither On Column and the r ACCEP	Ace. Cut ig on 2/22/84. GI. Q A/27/85 TED FOR RECORD