Form 3160-5 (December 1989)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: September 30, 1990

5. Lease Designation and Serial No.

	OF.	^7	07	00
NM	S-	07	X /	ΧIJ

SUNDRY NOTICES A	ND REPORTS ON WELLS	NMSF U/0/0U
Do not use this form for proposals to drill Use "APPLICATION FOR	or to deepen or reentry to a different reserved 16 17	6. If Indian, Allottee or Tribe Name
SUBMIT	N TRIPLICATE FEB 200	7. If Unit or CA, Agreement Designation
1. Type of Well	∞ OF CEIVE	3. Well rume and No.
OIL SAS WELL OTH	ER CON DI	Gallegos Canyon Unit 261
2. Name of Operator	201.3	9. APSWell No.
Amoco Production Company	Mary Corley	39-045-20044
3. Address and Telephone No.	10. Field and Pool, or Exploratory Area	
P.O. Box 3092 Houston, TX 77253	Pion Fruitland Sand Gas	
4. Location of Well (Footage, Sec., T., R., M., or Survey	11. County or Parish, State	
1650' FSL 1100' FEL Sec. 1	San Juan New Mexico	
12. CHECK APPROPRIATE BOX(s	S) TO INDICATE NATURE OF NOTICE, REPO	RT, OR OTHER DATA
TYPE OF SUBMISSION	ON	
Notice of Intent ■	Abandonment	Change of Plans
Subsequent Report	Recompletion	New Construction Non-Routine Fracturing
Final Abandonment Notice	Plugging Back Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other	
	Recompletion Report and Log fo	completion on Well Completion or orm.)
13. Describe Proposed or Completed Operations. (Cle	arly state all pertinent details, and give pertinent dates, including ace locations and measured and true vertical depths for all mark	ig estimated date of starting any proposed ters and zones pertinent to this work.)*
Amoco Production Company reques	t approval to plug and abandon the subject wel	l as follows:
 Notify regulatory agencies (BLM, indicate well is allotted (FIMO region 2. Check location for anchors. Insta 3. MIRUSU. Blow down well. Kill if 4. TOH with 1 1/2" tubing. Run in his Spot 100' cement plug on top of cement). NDBOP. Cut off casing and well 	NMOCD, FIMO) 24 hours in advance of pluggirulations effective April 1, 1997). Il if necessary. Test anchors. In ecessary with fresh water. NDWH. NUBOP. It is the blue with tubing and CIBP. Set CIBP at 1210'. To the light of the light of the light of the light of the location per instruction of the reclamation.	rest casing integrity to 500 psi. blug from 470' to surface (40 cuft State requirements.
14. I hereby certify that the foregoing is true and come Signed	Title Sr. Business Analyst	Date 02/10/00 Date FEB 5 2000