ROBERT L. BAYLESS

PETROLEUM PLAZA BUILDING
P. O. BOX 158
FARMINGTON, NEW MEXICO 87499
15051-326-2659

Horn Canyon #1 1190' FNL & 1055 FWL Sec. 26, T28N, R11W San Juan County, NM



OIL CON. DIV.

SLOPE TEST

Depth	Hole Deviation
120 ft.	1/4 degrees
650 ft.	1/4 degrees
1210 ft.	1/2 degrees
1725 ft.	3/4 degrees

) ss County of San Juan)	
I, Price M. Bayless, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.	
Subscribed and sworn before me this 21st day of August	19_95

1.0001, 100

My Commission Expires

State of New Mexico)

9-20-9/s

L & B Speed Drill, Inc.

James L. Ludwick

P.O. BOX 70 • FARMINGTON, NEW MEXICO 87499-0070 • (505) 325-1079

August 11, 1995

DECEIVED N AUG 2 2 1995

OIL COM. DIV.

ROBERT L. BAYLESS, PRODUCER P.O. BOX 168 FARMINGTON, NM 87499

RE: DEVIATION REPORT ON THE HORN CANYON WELL # 1, NW¹/₄, SEC. 28, T28N, R11W, SAN JUAN COUNTY, NM.

Below is the deviation report on your Horn Canyon Well #1.

120' 1/4°

650' 1/4°

1210' 1/2°

1725' 3/4°

SIGNED & ACKNOWLEDGE BY:_

JAMES L. LUDWICK, PRESIDENT

DATE: 8/11/95