

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator
MERIDIAN OIL

3. Address & Phone No. of Operator
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M
1190'FNL, 990'FEL Sec.31, T-29-N, R-4-W, NMPM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment

Type of Action

☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other -
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut off
☐ Conversion to Injection

13. Describe Proposed or Completed Operations

05-08-93 MOL&RU. Kill w/35 BW. SD for weekend.
05-09-93 Pump 30 BW. TOOH w/tbg. Set cmt ret @ 5988'. PT tbg 1500#. Load csg w/30 BW. Cmt w/119 sx Class "B" below ret, 5 sx cmt above ret. Pull to 5872'. Spot 39 bbl 9# 50 vis mud. Stand back.
05-12-93 Cut csg @ 3600'. Csg stuck. TIH w/cutter, cut csg @ 3476'. Csg stuck. TIH w/cutter, cut @ 2132'. Csg stuck. Permission f/W. Townsend @ 3:30 5-11-93 for change in procedure.
05-13-93 Spot 113 sx Cmt @ 4217-3209'. Pull up to 3062'. Spot 22 bbl 9# 50 vis mud to 2000'. TOOH. TIH, tag cmt @ 3342'. Shot 6 holes @ 2056'. Set cmt ret @ 2001', Cmt w/58 sx cmt below ret, 11 sx above. Displace w/6 BW. Pull to 1877'. Spot 38 bbl 9# 50 vis mud up to 225'. Shot 4 holes @ 225'. Circ out bradenhead. SDFN.
05-14-93 Set cmt plug w/122 sx cmt. Cut off WH. Install dry hole marker. Well plugged & abandoned.

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Affairs Date 5/14/93

(This space for Federal or State Office use)

APPROVED BY _____ Title _____

CONDITION OF APPROVAL, if any:

Date

APPROVED

MAY 18 1993

DISTRICT MANAGER

NMOCD