

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-039-07517
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	009257 San Juan 29-6 Unit
8. Well No.	San Juan 29-6 Unit #70
9. Pool name or Wildcat	Blanco Mesaverde 72319
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator Phillips Petroleum Company
3. Address of Operator 5525 Highway 64, NBU 3004, Farmington, NM 87401	4. Well Location Unit Letter <u>N</u> : <u>1150'</u> Feet From The <u>South</u> Line and <u>1500'</u> Feet From The <u>West</u> Line
5. Section <u>29</u> Township <u>29N</u> Range <u>6W</u> NMPM <u>Rio Arriba</u> County	6. Other: <u>Add Pay &amp; Stimulate</u> <input checked="" type="checkbox"/>

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: Add Pay & Stimulate ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NU BOP.  
POOH w/production tubing.

Isolate existing Mesaverde perms with retrievable bridge plug. Pressure test casing.

Perforate and stimulate Lewis Shale (perms to be determined after well logged). Retrieve RBP and run production tubing.

Flow test Lewis Shale.

A workover pit may be required.

RECEIVED  
FEB - 7 1997

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Patsy Clugston TITLE Regulatory Assistant DATE 2-3-97

TYPE OR PRINT NAME Patsy Clugston TELEPHONE NO. 505-599-3454

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY ERNIE BUSCH DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE FEB 10 1997  
CONDITIONS OF APPROVAL, IF ANY: Felaw Hueyfanito Bentonite