FOT (I	m 9-	881 a 951)	•	

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land O	ffice . N	w Ne:	cico	
		3471		
Unit	San	Juan	<i>2</i> 9-6	Unit
		08 -0 0		

1		CURCEOU	NY DEDA	APT OF WATER SHIIT OFF	X
l .	TO DRILL			ORT OF WATER SHUT-OFF	
	TO CHANGE PLANS			OR! OF ALTERING CASING	227
	N TO TEST WATER SHUT-OFF. N TO RE-DRILL OR REPAIR W			RT OF RE-DRILLING OR REPAIR	V #
	TO SHOOT OR ACIDIZE	SUBSEQUE	NT REPO	ORY OF ABANDONMENT JUN 1-5	
	TO PULL OR ALTER CASING	SUPPLEME	NTARY V	WELL HISTORY JUN 1 3	1959
	TO ABANDON WELL	l II		Otitica	
	(INDICATE ABOVE BY	CHECK MARK NATURE OF REP	ORT, NOT	rice, or other data)	-r 11:1
			_	June 11	, 19.55
والأراج الأجاسية	esc er	ft. from \\ \text{N} \\ \text{line a}	nd 1	6:0 ft. from E line of second E	. 2
	. No.) (Twp	· ·•		(Meridian)	
	Wildcat Dakota	(County or Subdivision)		(State or Territory)	
(Field)		(County of Subarvision)		(2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.	
State names of and exp	pected depths to objective sar	DETAILS OF WO	lengths	of proposed casings; indicate mudding	jobs, cement
n 6-4-59 Tota	al Depth 7897'.	nds; show sizes, weights, and nts, and all other important	lengths proposed	of proposed casings; indicate mudding d vork)	
on 6-4-59 Tota inn 15 Jointe sacks Pozmix	al Depth 7897'. 5', J-55, 15.00	nds; show sizes, weights, and all other important	lengths proposed	_ ·····	
on 6-4-59 Tota inn 15 Jointe sacks Pozmix	al Depth 7897'. 5', J-55, 15.00	nds; show sizes, weights, and all other important	lengths proposed	_ ·····	
n 6-4-59 Tota lan 15 Joints sacks Pozmix	al Depth 7897'. 5', J-55, 15.00	nds; show sizes, weights, and all other important	lengths proposed	_ ·····	
n 6-4-59 Tota lan 15 Joints sacks Pozmix '	al Depth 7897'. 5', J-55, 15.00	nds; show sizes, weights, and all other important	lengths proposed	_ ·····	
n 6-4-59 Tota lan 15 Joints sacks Pozmix	al Depth 7897'. 5', J-55, 15.00	nds; show sizes, weights, and all other important	lengths proposed	_ ·····	
on 6-4-59 Tota inn 15 Jointe sacks Pozmix	al Depth 7897'. 5', J-55, 15.00	nds; show sizes, weights, and all other important	lengths proposed	_ ·····	
n 6-4-59 Tota lan 15 Joints sacks Pozmix	al Depth 7897'. 5', J-55, 15.00	nds; show sizes, weights, and all other important	lengths proposed	_ ·····	
on 6-4-59 Totalism 15 Joints lands Pozmix ' Seld 1000#/30	al Depth 7897'. 5', J-55, 15.00 'S' 140; 1 1/4#'	nds; show sizes, weights, and all other important liner (5131) a Fine tuf-plug/ak	lengths proposed	on 7361' to 7694' vith	100
n 6-4-59 Totalian 15 Jointe sacks Formix Seld 1000#/30	al Depth 7897'. 5', J-55, 15.00 "S" 140; 1 1/4#	nds; show sizes, weights, and all other important liner (513') Fire tur-plus, ac	lengths proposed	_ ·····	100
on 6-4-59 Totalian 15 Jointe Sacks Formix Seld 1000#/30	al Depth 7897'. 5', J-55, 15.00 'S' 140; 1 1/4#'	nds; show sizes, weights, and all other important liner (513') Fire tur-plus, ac	lengths proposed	on 7361' to 7694' vith	100
An 15 Joints Secks Poznix Beld 1000#/30	his plan of work must receive the pl	nds; show sizes, weights, and all other important liner (513') Fire tur-plus, ac	lengths proposed	al Survey before operations may be com	100
I understand that the Company Address Box 9	his plan of work must receive the pl	nds; show sizes, weights, and all other important liner (513') a Fine tuf-plug, ac	lengths proposed	on 7361' to 7694' vith	100