

OIL CONSERVATION COMMISSION

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO

OK

October 3, 1962

*El Paso Natural Gas Company
Box 990
Farmington, New Mexico*

Attn: Mr. E. S. Oberly

*RE: EPNG #2 Bolin, SW 5-29N-7W
Blanco Mesaverde Pool*

Gentlemen:

*Bradenhead test submitted to this office July 25, 1962
shows definite indication of casing failure.*

*You are, therefore, directed to take action to repair the
casing in this well.*

Yours very truly

*Emery C. Arnold
Supervisor, District #3*

ECA:ks

*cc: Oil Conservation Commission
Santa Fe, New Mexico*

*Lew Galloway
EPNG, Farmington, N.M.*

JOINT OBSERVATION COMMISSION
ON THE BRASS BELL
AT THE NEW MEXICO

THE BELL

THE BELL
THE BELL
THE BELL

THE BELL
THE BELL

THE BELL

THE BELL
THE BELL

THE BELL
THE BELL

THE BELL

THE BELL
THE BELL

THE BELL

THE BELL
THE BELL

THE BELL
THE BELL

NEW MEXICO OIL CONSERVATION COMMISSION
1000 Rio Brazos Road
Aztec, New Mexico

1/2

BRADENHEAD TEST REPORT

(Submit 3 copies to above address)

Date of Test 6-27-62 Operator El Paso Natural Gas Company

Lease Name Bolin Well No. 2 Location U SW Sec. 5 Twp. 29 Rge. 7

Pressure (Shut-in or ~~Flowing~~) Dwt. Tubing 644 Casing 102 Bradenhead 87
(After Equalizing 245)

OPEN BRADENHEAD TO ATMOSPHERE FOR 15 MINUTES.

Casing or Tubing Pressure, Dwt.

Bradenhead Flowed:

5 Min. 100

Steady Flow

10 Min. 96

Surges

15 Min. 94

Down to Nothing

20 Min. 271

Nothing

⁵
~~25~~ Min. 328

Gas X

¹⁰
~~30~~ Min. 350

Gas & Water

15 Min. 370

Water

If Bradenhead flowed water check description below:

Clear

Remarks: Will workover to repair casing

Fresh

leak.

Salty

Sulfur

Black

By Arthur J. Connelly

Gas Tester
Position

Witness ~~XXX~~ Fred Cook (OCC)

