

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Federal <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-	7. Unit Agreement Name San Juan 29-6 Unit
2. Name of Operator El Paso Natural Gas Company	8. Farm or Lease Name
3. Address of Operator Box 990, Farmington, New Mexico	9. Well No. 12
4. Location of Well UNIT LETTER H , 1650 FEET FROM THE North LINE AND 990 FEET FROM THE East LINE, SECTION 6 TOWNSHIP 29 RANGE 6W NMPM.	10. Field and Pool, or Wildcat Blanco Mesa Verde
15. Elevation (Show whether DF, RT, GR, etc.) 6802' GL	12. County Rio Arriba

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER Workover & Recompletes <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Due to a casing leak, it is intended to workover and recomplete this well in the following manner:

Pull tubing and clean out to total depth.

Perforate and squeeze the Ojo Alamo formation

Run and cement 4 1/2" casing

Perforate and fracture selective zones in the Mesa Verde formation.

If the tubing cannot be pulled, the open hole will be squeezed and the hole whipstocked through the Mesa Verde formation.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED **OR OTHER SIGNED E. S. OBERLY** TITLE **Petroleum Engineer** DATE **10-4-65**

APPROVED BY **Emery C. Carver** TITLE **Sup. Dist. 115** DATE **10-5-65**
CONDITIONS OF APPROVAL IF ANY: