

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" (for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Southland Royalty Company	8. FARM OR LEASE NAME LaBaca
3. ADDRESS OF OPERATOR Post Office Box 4289, Farmington, NM 87499	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 790'N, 820'E	10. FIELD AND POOL, OR WILDCAT Blanco Mesa Verde
14. PERMIT NO.	11. SEC., T., R., M., OR BLE. AND SURVEY OR TIES Sec. 1, T. 29-N, R- 5, N.M.P.M.
15. ELEVATIONS (Show whether OF, ST, OR, etc.) 7614'GL	12. COUNTY OR PARISH 13. STATE Rio Arriba NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	(Other) ☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. USE: RIDE PROPOSED OR COMPLETED OPERATIONS (Indicate state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

It is intended to plugback the Mesa Verde to the Fruitland Coal in the following manner:

MOL&RU. Set bridge plug at 6660'. Spot cement from 6660-6610'. Set bridge plug @ 4535'. Perforate squeeze holes @ 4525'. Set squeeze packer @ 4513', and squeeze with cement to bring cement top to 3740'. Release squeeze packer. Perforate and fracture Fruitland coal zone. Clean well out, and land 2 3/8" tbg near 4480'. Rig down and release rig. This work is planned to be completed by August 1, 1989.

RECEIVED
FARM MAIL ROOM

09 FEB 16 PM 1:16

FARMINGTON RESOURCE AREA
FARMINGTON, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Regulatory Affairs ()

DATE

Feb. 16, 1989

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

DATE

FEB 27 1989

AREA MANAGER

*See Instructions on Reverse Side