## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

	****		
DISTRIBUTION			
BANTA PE		1	
FILE			
U.S.G.S.			
LAND OFFICE			
TRANSPORTER	OIL		
	GAS	1 1	
OPERATOR			
PROBATION OFFICE			$\neg$

## OIL CONSERVATION DIVISION P. O. BOX 2088 SANTA FE, NEW MEXICO 87501

Form C-104 Revised 10-01-78 Format 06-01-83 Page 1

Separate Forms C-104 must be filed for each pool in multip-completed wells.

OPERATOR PROBATION OFFICE	• •	FOR ALLOWABLE AND	UDAL GAS	
I. Operator	AUTHORIZATION TO TRAN	SPURT OIL AND NAT	URAL GAS	
Northwest Pipeline Corp	oration			
P.O. Box 90 - Farmington Resson(s) for liling (Check proper box)	n, New Mexico 8749		te expiain)	
New Well Recompletion	Change in Transporter of:	Dry Gas		
If Change of ownership give name and address of previous owner	Casinghead Gas	Condensate		
II. DESCRIPTION OF WELL AND LI	EASE   Well No.   Pool Name, Including			
San Juan 29-6 Unit	25A Blanco Mesa		Kind of Lease State, Franky XXXX	E- 289-36
	Feet From The East L	.ine and1150	Feet From The Sout	;h
Line of Section 32 Township	p 29N Range	6W , NMPN	. Rio Arriba	County
III. DESIGNATION OF TRANSPORT	TER OF OIL AND NATURA	AL GAS	to which approved copy of thi	is form is to be sent)
Four-Four Inc.	ed Gas or Dry Gas [V]	P.O. Box 821	- Farmington, NM	87499
Northwest Pipeline Corpo			- Farmington, NM	87499 -
If well produces oil or liquids, give location of tanks.	) 32 29N 6W			
If this production is commingled with the NOTE: Complete Parts IV and V on		, give commingling orde	r number:	<del></del>
VI. CERTIFICATE OF COMPLIANCE		OIL C	ONSERVATION DIVIS	VPN 0 1000 :
I hereby certify that the rules and regulations of been complied with and that the information given my knowledge and belief.	Doife of the food of the first of	APPROVED	Frank JO	<u>v 1 0 1986</u>
	JUN 1 0 1986	TITLE	SUPERVISOR DISTRIC	
Cara Hain 10.	OIL CON. DIVE	If this is a requ	be filed in compliance w	wiv drilled or deepen
Production & Drilling Cl		tests taken on the	the accompanied by a tab well in accordance with R this form must be filled or	ULE 111.
May 30, 1986		Fill out only S	completed wells.	for changes of owns
(5011)		well name or number	, or transporter, or other su	ch change of conditic