NORTHWEST NEW MEXICO PACKER-LEAKAGE TEST

Operator Tu	all Popo	WCTIPUL CON	e Le	ase Shern	nAN	No. 2	
Location	,-	2 - 20	?N Rge	<u></u>	County	Pro Acriba	
of Well: Unit	E_Sec	Twp. 27	Type of Prod.	Method o	f Prod.	Prod. Medium	
<u> </u>	ame of Reser	rvoir or Pool	(Oil or Gas)	(Flow or A	rt. Lift)	(Tbg. or Csg.)	
Tinnon.			GAS Floo			Tbq.	
Lower Completion M			GAS LON SHUT-IN PRE	Floa	J	T69.	
Completion 7.7	- JAVENO	PRE-F	LON SHUT-IN PRE	SSURE DATA		Stabilized?	
Upper Hour, da Compl Shut-i		5 Length	of t-in 3days	SI press	•	(Yes or No)	
Lower Hour, da	te 9-23-85					Stabilized?	
Compl Shut-i			t-in 3dAys FLOW TEST NO	psig	650	(Yes or No)	
Conmenced at (hour, date)	* 9-26-85		Zone pro	ducing- (Upp	er or Lower):	
	ed at (hour, date)* 9-26-85 2:20 pm e Lapsed time Pressure date) since* Upper Compl. Lower Compl		sure Compl	Prod. Zone		Remarks	
(hour, date)	since*			Temp.	nto.		
9-27-85	1 day	480	300				
1:10 PM	2 days	480	295				
9-28-85	Zunys	1 / 55					
J		<u> </u>					
Production rat		st ased on	Bbls. in	Hrs.	. Gr	av. GOR_	
0il:	8	MCFPD: Tested	thru (Orifice 4	or Met er):			
			EST SHUT-IN PRI	ESSURE DATA SI press		Stabilized?	
Upper Hour, date Compl Shut-in			Length of time shut-in			(Yes or No)	
Lower Hour, date		Length	Length of		5•	Stabilized? (Yes or No)	
Compl Shut-	<u>in</u>	time shu	FLOW TEST NO	psig 0.2			
Commenced at	(hour, date)	**		Zone pro	oducing (Upp	er or Lower):	
Time	Lapsed time	Pres	Lower Compl.	Prod. Zone Temp.	Re	marks	
(nour, date)	SHICE WA	Jobel Comet					
							
						97205 - 1287 - 1	
					District.		
Production ra	te during te	st.		1	~/.	<u>, v</u>	
Oil:	BOPD b	pased on	Bbls. in_	Hrs.	Grav	GOR	
Gas:		MCFPD; Tested	i thru (Orifice	or Meter):_			
REMARKS:							
The state of the s							
harahy cartif	v that the	information he	erein contained	is true and	complete t	o the best of my	
knowledge.			•		P	-10-00	
	SEP 3	3 0 1985.	Operato	r NugAN	1 FODUCE	on Joer.	
Approved: Oil Conservati	on Division	13	By M	r Dugan	71 KM	ler)	
Ozininal S	ia and he curners	Cuntage	T;+1^	1			
ByOriginal S	igued by CHARLES	GHOLSON		9-30-85			

thereafter as prescribed by the order wiltiple completion. tests shall also be commenced on all multiple completions within a days following recompletion and/or chemical or fracture treatment seven days following recorpletion and/or chemical or fracture treatment, and whenever recoded work has been done on a well during which the packer or the fubing have been disturbed. Tests shall also be taken at any that consummation is suspected or when requested by the Commission. at least 72 hours prior to the commencement of any packer leakage operator shall notify the Commission in writing of the exact time operator shall notify the Commission in writing of the exact time of is to be commenced. Offset operators shall also be so notified. The packer leakage test shall commence when both zones of the dual the exact time the 3. The packer leakage test shall commence when both zones of the dual concletion are shut-in for pressure stabilization. Both zones shall resum shut-in until the well-head pressure in each has stabilized, provided however, that they need not remain shut-in more than seven days.

4. For flow lest to, 1, one zone of the dual completion shall be produced at the normal rate of production while the other zone remains shut-in. Such test shall be continued for seven days in the case of a gas well and for 24 hours in the case of an oil well. Note: if, on an initial packer leakage test, a gas well is being flowed to the atmosphere due to the lack of a pipeline connection the flow period shall be three hours.

5. Following completion of flow fest No. 1, the well shall again be shut-in, in accordance with Paragraph 3 above.

6. Flow lest No. 2 shall be conducted even though no leak was indicated 6. Flow Test \0. 2 shall be conducted even though no leak was indicated during Flow Test \0. 1. Procedure for Flow Test \0. 2 is to be the same as for Flow Test \0. 1 except that the previously produced zone shall remain shut-in while the zone which was previously shut-in is produced.

deadwright pressure gauge at time intervals in follows: 3 bours tests: immediately prior to the beginning of each flow-period, at fifteen-minute intervals during the first bour thereof, and at bourly intervals thereafter, including one pressure measurement immediately prior to the conclusion of each flow period. 7-day tests: immediately prior to the beginning of each flow period, at least one time during each flow period (at approximately the midway point) and immediately prior to the conclusion of each flow period. Other pressures may be taken as desired, or may be requested on wells which have previously shown questionable test data.

Pressures for gas-zone tests must be measured on ear deadweight pressure gauge at time intervals as fullows:

data.

24-hour oil zone tests: all pressures, throughout the entire test, shall be continuously measured and recorded with recording pressure gauges the accuracy of which must be checked at least twice, once at the beginning and once at the end of each test, with a deadweight pressure gauge. If a well is a gas-oil or an oil-gas dual completion, the recording gauge shall be required on the oil zone only, with deadweight pressures as required above being taken on the gas zone.

8. The results of the above-described tests shall be filed in triplicate within 15 days after completion of the test. Tests shall be filed with the Aztec District Uffice of the New Pexico Oil Conservation Commission on Northwest New Mexico Packer Leakage Test form Revised 11-1-58, with all deadweight pressures indicated thereon as well as the flowing temperatures (gas zones only) and gravity and COR (oil zones only). A pressure versus

(gas zones only) and gravity and GOR (oil zones only). A pressure versus time curve for each zone of each test shall be constructed on the reverse side of the Packer Leakage Test form with all deadweight pressure points taken indicated thereon. For oil zones, the pressure curve should also indicate all key pressure changes which may be reflected by the recording gauge charts. These key pressure changes should also be tabulated on the

upper - SI hower- Flaudront of the Packer Leakage Test Form. Roth Zones Shut IN 1000 Psi 900 Psi 800 700 Psi Mesaveide Formation 600 PSI 500 75 Tured CASTS FORMATION 400 300. P5i 200 100.