Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office		•	Revised 1-1-89
<u>DISTRICT I</u> P.O. Box 1980, Hobbs NM 88241-1980	OIL CONSERVATI 2040 Pachec		WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, NM		30-039-21325 5. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			STATE FEE X 6. State Oil & Gas Lease No.
			o. State on & Gas Lease 140.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name 009257
1. Type of Well: OlL GAS 571			San Juan 29-6 Unit
OIL GAS WELL X	OTHER	017654	
2. Name of Operator			8. Well No.
Phillips Petroleum Company	· · · · · · · · · · · · · · · · · · ·		SJ 29-6 Unit #45A
3. Address of Operator 5525 Highway 64, NBU 3004, F	armington NM 87401		9. Pool name or Wildcat Blanco Mesaverde 72319
4. Well Location Unit Letter I : 1650	Feet From The South	Line and99	O' Feet From The East Line
Section 27	Townshin 29N I	Range 6W	NMPM Rio Arriba County
Section 21	TABLE TO THE TABLE	Range OW her DF, RKB, RT, GR, etc	
11. Check An	proprieto Por to Indicate	Nature of Nation	Papart or Other Data
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON —	CHANGE PLANS L_	COMMENCE DRILLING	
PULL OR ALTER CASING L		CASING TEST AND CE	
OTHER:		OTHER: Add P	ay and Stimulate X
 Describe Proposed or Completed Oper work) SEE RULE 1103. 	ations (Clearly state all pertinent de	etails, and give pertinent da	tes, including estimated date of starting any proposed
Attached is the procedure formation on the subject		timulate the Lewis	Shale interval in the Mesaverde
		(B)	EIVED 2 1998 2010 DIV
		APR	- 2 1998
		JU AIN	and Diffe
			DIRING 3
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE FACE	Chis To	TLE Regulatory	Assistant DATE 4-1-418
TYPE OR PRINT NAME Pa-	tsy Clugston	a section of	TELEPHONE NO. 505-599-3454
(This space for State Use)			

TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #BATE APR 1 3 1998

San Juan 29-6 #45A Fee; Unit I, 1650' FSL & 990' FEL Section 27, T29N, R6W; Rio Arriba County, NM

Procedure used to perf & stimulate the Lewis Shale interval in the existing Mesaverde formation.

3/11/98

MIRU Big A #40. Killed well. ND WH & NU BOPs. COOH w/2-3/8" tubing. RIH w/bit & scraper and tag at 5535'.

RIH w/4½" RBP & set @ 4900'. Load hole w/2% KCL water and test casing & CIBP to 500 psi Good test. Ran GR/CCL/CBL (4900 to surface). RU Blue Jet & perf'd Lewis Shale @ 1 spf .38" holes - 120° phasing. (Logs indicate Heufinito Bentonite @ 3873').

4482'-4487' (5'); 4375'-4380' (5'); 4350'-4355'(5'); 4278'-4283' (5'); 4226'-4231' (5'); 4210'-4215'(5'); 4128'-4133'(5'); Total 35 Holes

RIH & set packer @ 3946'; Load and test casing & packer to 500 psi – good test. RU BJ to acidize. Pumped 1000 gal of 15% HCL acid w/54 ballsealers. Released packer and knocked balls off perfs. COOH w/tubing and packer. NU BOP. GIH w/4½" fullbore packer and set @ 3430'.

RU to frac. Pumped 57,153 gal 2% KCl w/30# gel, 201,000 # 20/40 Brady sand, 820,000 scf of N_2 , w/60% Quality foam. Avg. pressure 2750#; Avg. rate 45 bpm, ISDP 400#. Flowed back immediately on ¼" and ½" choke. Flowed back for approx. 47 hrs.

Unseat packer & COOH. Cleaned out fill and drilled out CIBP. Cleaned out to PBTD @ 5535'. COOH. RIH w/2-3/8" production string – circulated out fill. Landed tubing @ 5474' with "F" nipple @ 5441'. ND BOPs & NU WH. Pumped off exp. Check. RD & released rig. Turned well over to production department.