n 3160-5

UNITED STATES

FORM APPROVED
Budget Bureau No. 1004-0135

DEPARTM	ENT OF THE INTERIOR	Expires: March 31, 1993
uic 1990)	F LAND MANAGEMENT	5. Lease Designation and Serial No.
SUNDRY NOTICES AND REPORTS ON WELLS		SF-080146
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.		6. If Indian, Allottee or Tribe Name
	OR PERMIT - " for such proposals	
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
I. Type of Well		San Juan 29-6 Unit
Oil X Gas Other		8. Well Name and No.
2. Name of Operator		SJ 29-6 Unit #7A
Phillips Petroleum Company		9. API Well No. 30-039-21367
3. Address and Telephone No. 5525 Highway 64, NBU 3004, Farmington, NM 87401 505-599-3454		10. Field and Pool, or exploratory Area
Location of Well (Footage, Sec., T., R., M., or Surve		
Unit E, 1530' FNL & 895' FWL		Blanco Mesaverde 11. County or Parish, State
Section 34, T29N, R6W		Rio Arriba, NM
	WENT TO INDICATE MATURE OF NOTICE DEPORT	1.1.1
CHECK APPROPRIATE BO	X(s) TO INDICATE NATURE OF NOTICE, REPORT	
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
₩	Recompletion	New Construction Non-Routine Fracturing
X Subsequent Report	Plugging Back	Water Shut-Off
Final Abandonment Notice	Casing Repair Altering Casing	Conversion to Injection
	X Other Add Pay and Stimulat	e Dispose Water
		(Note: Report results of multiple completion on V Completion or Recompletion Report and Log for
See attached for the procedure u Lewis Shale pay and stimulate bo	used add additional perfs the existing Mesavero oth the new perfs in the Mesaverde zone and Lew	de interval and then add vis Shale interval.
	UEGEIME!	
	Ш <u>Ш</u> МАУ 1 2 1998 і	
	- 1000	••
	OIL CON. DIY	<u>% </u>
14. I hereby certify that the foregoing is true and correct	DIST. 3	5-3-98
Signed # Alisy Coll	Title Regulatory Assistant	Date - 3-3-90
(This space for Federal or State office use)	γ 4	withith lay recorf
Approved by	Title	Date -
· · · · · · · · · · · · · · · · · · ·		MAY 0 8 1998
Title 18 U.S.C. Section 1001, makes it a crime for any	person knowingly and willfully to make to any department or agency of the Ur	nited States any false, fictitious or fraudulent state
or representations as to any matter within its jurisdiction		AMINGTON DISTRICT OFFICE

* See Instruction on Reverse Side

San Juan 29-6 #7A SF-080146; Unit E, 1530' FNL & 895' FWL Section 34; T29N, R6W; Rio Arriba County, NM

Procedure used to re-perf part of the Mesaverde interval and perf the Lewis Shale interval and then stimulate both intervals.

4/11/98

MIRU Big A #40. Killed well. ND WH & NU BOPs. COOH w/2-3/8" tubing. RIH w/bit & scraper and tag at 5567' (PBTD). COOH. RIH w/4½" CIBP & set @ 5275'. RU Blue Jet & perf'd Mesaverde @ 1 spf .31" holes. Perf'd as follows:

```
5261', 5258', 5252', 5245', 5240' 5195' 5193', 5183', 5177', 5173', 5165', 5161', 5159', 5155', 5121', 5055', 5043', 5020', 4997', 4993', 4983', 4976' @ 1 spf Total 22 holes
```

Total 30 perfs open now including ones @ 5238', 5131', 5126', 5058', 5052', 5046', 5040', 4995'.

RIH & set 4-1/2" Fullbore packer @ 4829'; Load casing and test casing & packer to 500 psi - good test.

RU BJ to acidize Mesaverde intervals 4995' – 5261 w/30 bbls 7½% HCl and ballsealers. Released packer and knocked balls off perfs. COOH w/tubing and packer. NU BOP. GIH w/4½" fullbore packer and set @ 4860'. Roll hole with 100 bbls 2% KCl water & PT casing & BP to 500 psi – held OK. COOH.

GIH w/GR-CCL-CBL & tagged BP @ 4856'. Logged from 4856' – 3470 (liner top) w/o pressure – good cement to liner hanger. Logged under 250 psi from 3470' – surface. Good bond from 3470' – 2100'; 40-60% from 2100' – 1100', and good bond from 1100-300' surface casing.

GIH to perforate Lewis Shale formation @ 1 spf (0.31") Diam. (36 holes) as follows: (Huerfanito Bentonite not present, equivalent stratigraphic depth is @ 3628').

```
4549'-4552' (3'); 4403'-4406'(3'); 4354'-4357'(3'); 4284'-4287' (3'); 4246'-4249' (3'); 4238'-4241' (3'); 4214'-4217'(3'); 4128'-4131' (3'); 4061'-4064' (3'); 4025'-4028' (3'); 3989'-3991' (3'); 3923'-3926' (3');
```

Pulled up packer to 3769' & set. Load casing & PT to 500 psi. RU to acidize Lewis Shale interval. Pumped 1000 gal 15% HCL w/ballsealers. Released packer & GIH to 4590' and knocked off balls. COOH & laid down packer.

RIH w/4 ½" FB Packer & set @ 3509'. Load casing & PT packer to 400 psi – OK. RU to frac. Pumped 73,910 gal of 2% KCL water w/30# X-link 60 Quality N2 foam w/200,000# 20/40 Brady sand. Total 911,300 scf N2. ATP 2050 psi. ATR 45 bpm; ISIP – 500 psi. Flowed back immediately on ¼" & ½" choke. Flowed for @ 44 hrs.

RD. Unseat packer & COOH. Cleaned out fill and drilled out CIBP @ 4860' & 5275'. Cleaned out wellbore. COOH. RIH w/2-3/8" production string and landed tubing @ 5515' with "F" nipple @ 5482'. ND BOPs & NU WH. Pumped off exp. Check. RD & released rig. Turned well over to production department 4/22/98.