

Form 3160-5
(June 1990)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT - " for such proposals

5. Lease Designation and Serial No.

SF-078278

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

San Juan 29-6 Unit

8. Well Name and No.

S J 29-6 #227R

9. API Well No.

30-039-25418

10. Field and Pool, or exploratory Area

Basin Fruitland Coal

11. County or Parish, State

Rio Arriba, NM

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Phillips Petroleum Company

3. Address and Telephone No.

5525 Highway 64, NBU 3004, Farmington, NM 87401

505-599-3454

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit K, 2503' FSL & 1816' FWL
Section 14, T-29-N, R-6-W

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☒ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other
- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

A-Plus Well Service plugged the subject well on 12-15-95 per the attached report.

RECEIVED
JAN 16 1996
OIL CON. DIV.
DIST. 3

RECEIVED
JAN 16 1996
OIL CON. DIV.
DIST. 3

14. I hereby certify that the foregoing is true and correct

Signed

E. H. H. H.

Title

Enviro./Regulatory Engineer

Date

1-2-96

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

* See Instruction on Reverse Side

NMOCD

APPROVED
JAN 16 1996
DISTRICT MANAGER

Phillips Petroleum Company
San Juan 29-6 Unit #227R (FtC)
2503' FSL, 1816' FWL, Sec. 14, T-29-N, R-6W
Rio Arriba County, NM.
SF-078278

December 18, 1995

Plug & Abandonment Report

Cementing Summary:

Plug #1 with retainer at 3420', spot 29 sxs Class B cement inside 7" casing from 3420' to 3262' above retainer to isolate Fruitland Coal formation.

Plug #2 with 68 sxs Class B cement inside casing from 3038' to 2675' over Ojo Alamo top.

Plug #3 with 29 sxs Class B cement inside casing from 1526' to 1375' over Nacimiento top.

Plug #4 with 60 sxs Class B cement inside 7" casing from 301' to surface, circulate 1 bbl good cement out casing valve.

Plugging Summary:

12-13-95 Drive rig and equipment to location. Spot rig and equipment on location. RU rig and equipment. SDFD.

12-14-95 Safety Meeting. RD wellhead. Check well pressure: 500#. Install pit liner. Lay out relief lines to pit. Bleed well down to 50#. Pump 40 bbls water down casing to kill well. ND wellhead. NU BOP and function test. PU 7" hydro set cement retainer and RIH with 108 joints tubing; set retainer at 3420'. Circulate casing with 116 bbls treated water (1/2% CRW037 corrosion inhibitor). Pressure test casing to 500# for 15 min, held OK. Plug #1 with retainer at 3420', spot 29 sxs Class B cement inside 7" casing from 3420' to 3262' above retainer to isolate Fruitland Coal formation. POH to 3038'. Establish circulation. Plug #2 with 68 sxs Class B cement inside casing from 3038' to 2675' over Ojo Alamo top. POH to 1526'. Shut in well. SDFD.

12-15-95 Safety Meeting. Open up well, no pressures. Establish circulation with 5 bbls water. Plug #3 with 29 sxs Class B cement inside casing from 1526' to 1375' over Nacimiento top. POH to 301'. Establish circulation. Plug #4 with 60 sxs Class B cement inside 7" casing from 301' to surface, circulate 1 bbl good cement out casing valve. POH and LD tubing. Shut in well and WOC. RD floor. Dig out wellhead. ND BOP. Cut wellhead off. Found cement at surface in 7" X 9-5/8" casing annulus. Mix 25 sxs Class B cement and install P&A marker. RD rig and move off location. Notified BLM at 2:00 PM on 12-13-95. J. Morris with BLM was on location.