

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
811 South First, Artesia, NM 87210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-039-26179
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator Phillips Petroleum Company		6. State Oil & Gas Lease No.
3. Address of Operator 5525 Highway 64, NBU 3004, Farmington, NM 87401		7. Lease Name or Unit Agreement Name: San Juan 29-6 Unit 009257
4. Well Location Unit Letter <u>C</u> : <u>755'</u> feet from the <u>North</u> line and <u>1380'</u> feet from the <u>West</u> line Section <u>3</u> Township <u>29N</u> Range <u>6W</u> NMPM County <u>Rio Arriba</u>		8. Well No. SJ 29-6 Unit #29B
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. Pool name or Wildcat Basin Dakota and Blanco MV

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: PT CIBP to keep DK TA status - 5 years ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

3/26/02 MIRU Key #940. ND WH & NU BOP. PT-OK. COOH w/tubing. RIH w/FBP & set @ 5720'. Load w/water. PT CIBP & tbg to 500 psi. Pressure increased to 920 psi as water temperature increased to wellbore temperature. Recorded pressure on chart (attached). Held 30 minutes. Released packer. COOH w/packer. RIH w/2-3/8" 4.7# tubing and set @ 5487' w/"F" nipple set @ 5479'. ND BOP, NU WH. RD & released rig 3/27/02.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Patsy Clugston TITLE Sr. Regulatory/Proration Clerk DATE 4/3/02

Type or print name Patsy Clugston Telephone No. 505-599-3454

(This space for State use)  
APPROVED BY Charles R. TITLE APR - 5 2012 DATE   
Conditions of approval, if any: