-			*****	-
Form 9-3 (May 19)	31 63)	JNITED STATES	SUBMIT IN TRIPLICATE*	Form approved. Budget Bureau No. 42-R1424.
,	DEPARTM	MENT OF THE INTE	RIOR (Other instructions on re-	5. LEASE DESIGNATION AND SERIAL NO.
	G	S.F.078049		
	SUNDRY NOTI	6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
((Do not use this form for proposa Use "APPLICA"			
ī.		1101, 101, 101, 101, 101, 101, 101, 101	,	7. UNIT AGREEMENT NAME
OIL WELI	GAS OTHER		AUG 1 5 1967	
	OF OPERATOR	· · · · · · · · · · · · · · · · · · ·	OIL CON. COM.	8. FARM OR LEASE NAME
	Jerome P. McH	ugh	DIST. 3	Hardie
3. ADDR	ESS OF OPERATOR	9. WELL No. 2		
4. LOCA	Box 234, Farm	10. FIELD AND POOL, OR WILDCAT		
See a	ilso space 17 below.) urface	Basin Dakota		
	970' FNL, 850	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA		
		'		South of Alle
14. PERM		[15 B. D. T. (01)		Sec28;T29N,R8W, NMPM
14. PERM	IT NO.	15. ELEVATIONS (Show whether		San Juan New Mexico
16.	Check Appropriate Sex To Indicate Nature of Notice, Report, or Other Data			
	NOTICE OF INTENT	E OF INTENTION TO:		ENT REPORT OF:
TES	T WATER SHUT-OFF	CLL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRA	CTURE TREAT M	ULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
		BANDON*	SHOOTING OR ACIDIZING	Come to Come X
		HANGE PLANS	(Other) (Norm: Report results	of multiple completion on Well
17. DESC	her)	RATIONS (Clearly state all perti	neut details, and give pertinent dates.	etton Report and Log form.) including estimated date of starting any
pr	oposed work. If well is direction int to this work.) *	ally driffed, give subsurface l	locations and measured and true vertical	di depths for all markers and zones perti-
8-2-67	PSTD 7568. Ran We	lex Gamma Ray corr	relation log - pressure	test casing. well head
	and BOP to 4000 ps	i - held O.K.		
			5 - 47, 7533 - 35, 75	522- 24 and 7510 - 12.
			R. 35 B/M at 4000 psi.	
	Instant shut in pro		75-77, 7458 - 60, 7 42	22 - 28 and 7388 - 90
			0 sd. 25,200 gal. wat	
				nal 3300 psi. Immediate
	shut in 1400 psi.	Ave. I.R. 49 BPM,	parf. 2 jets per ft. 7	7311-13 and 7294-95.
	Frac all perf. w/	60,000 lbs. 20-49	sd, 65,620 gal. water w	// 2 1/2# J-100 per
	1000 gal. I.F.P.	3700 psi, min. 320	00 psi, max 4500 psi, Av	e. 4000 psi, Final
	4000 psi, Max. I.R.			
	Drop 8 balls, press		it in press. 1200 psi	
			acid, pressure broke ba	ack 500 psi
			Shut well in for I how	
	Open well to pit -	well kicked off d	luring night, making esi	. 2600 MCF with heavy
	spray water.			
0 2 67	DOTE 7560 Daw 24.	4 sta 1 1//80 0	2 44 VCO EE 100 FUT Vo.	
8-3-67			2.4# YCO-55 10R EUE Yoused rig 4:00 PM 8-2-67.	
10.71				ORGE WELL HIL
	eby certify that the foregoing is	<i>[1]</i>	Engineer	8–11–67
SIGN	TED MEMAN HI	Wegan- TITLE_	ruà meet	DATE
(Thi	s space for Federal or State office	e use)		
APP	ROVED BY	TITLE _	·	PECEIVED
	DITIONS OF APPROVAL, IF A			IVECEIVED

*See Instructions on Reverse Side