


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe**
Lease No. **076132**
Unit **A. L. Elliott "C"**



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	X	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 25, 19**57**

Well No. **1** is located **990** ft. from **[N]** line and **1650** ft. from **[E]** line of sec. **15**
NE/4 of Section 15 **T-29-N** **R-9-W** **N.M.P.M.**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Blanco-Mesa Verde **San Juan** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **5937** ft. (G.L.)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We propose to workover the above well as follows:

1. Move in and rig up workover rig.
2. Cleanout hole with gas to total depth, or whipstock hole, if necessary.
3. Run 5" liner to total depth and cement.
4. Drill out cement and perforate selected zones.
5. Stimulate with sand-water frac.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **PAN AMERICAN PETROLEUM CORPORATION**

Address **Box 457, Farmington, New Mexico**

By **L. D. Sperry**

Title **Field Superintendent**