Formerly 9-33:)	PARTMENT OF THE INTERIOR (Other 1)	Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL BO.
	BUREAU OF LAND MANAGEMENT / NOTICES AND REPORTS ON WELLS for proposals to drill or to deepen or plug back to a different "APPLICATION FOR PERMIT—" for such proposals.)	
1. •IL [] 4A8 [V]		7. UNIT AGREEMENT NAME
WELL WELL LA	- OTERS	S. PARM OR LEASE HAME
Tenneco Cil Compa	any	Hamner
B. ADDRESS OF OFTEATOR D.O. ROY 32/10 Fr	nglewood, CO 80155	9. WHEL NO.
LOCATION OF WELL (Report	location clearly and in accordance with any State requiremen	
See also space 17 below.) At surface	RECEI	0.14 44.14
1190' FSL, 2130'	MAY 2 1 19	11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA
	•	Con 20 T20N DOU
14. PERMIT NO.	15. REVATIONS (Show PARKINGTON WE'SOL	JRCE AREA 12. COUNTY OR PARISE 13. STATE
	5698' GR	San Juan NM
16. C	heck Appropriate Box To Indicate Nature of Noti	ce, Report, or Other Data
NOTICE	OF INTENTION TO:	SUBSEQUENT EXPORT OF:
TEST WATER SEUT-OFF	PULL OR ALTER CABING WATER S	EUT-OFF ESPAIRING WELL
PRACTURE TREAT	MULTIPLE COMPLETE PRACTURE	TREATMENT ALTERING CASING
SHOOT OR ACIDIZE		Re-Completion
		orn: Report results of multiple completion on Well
proposed work. If well i	LETED OPERATIONS (Clearly state all pertinent details, and gi	npiction or Recompletion Report and Log form.) ive pertinent dates, including estimated date of starting any red and true vertical depths for all markers and nones perti-
(Other) 17. DESCRIBE PROPISED OR COMPINED TO PROPOSED WORK. If well sent to this work.) 05/11/84: MIRUSU 05/14/84: RIH w/ RIH w/4-1/2" Mode	LETED OPERATIONS (Clearly state all pertinent details, and give subsurface locations and measured. Let's well NDWH. NUBOP. (2-3/8" tbg, opened. Tagged w/fill @	npletion or Recompletion Report and Log form.) ive pertinent dates, including estimated date of starting any red and true vertical depths for all markers and sones perti- 6008'. CO to PBTD @ 6058 w/foam. 6560'. Loaded hole w/wtr. Press tst
(Other) 17. DESCRIBE PROPISED OR COMPRISED	LETED OPERATIONS (Clearly state all pertinent details, and give in directionally drilled, give subsurface locations and measure. J. Killed well NDWH. NUBOP. Z2-3/8" tbg, opened. Tagged w/fill @ el D prod pkr w/exp plug. Set plug @	npletion or Recompletion Report and Log form.) ive pertinent dates, including estimated date of starting any red and true vertical depths for all markers and sones perti- 6008'. CO to PBTD @ 6058 w/foam. 6560'. Loaded hole w/wtr. Press tst