

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY


SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. SF 079012
2. NAME OF OPERATOR Northwest Pipeline Corporation		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. Box 90 Farmington, New Mexico 87401		7. UNIT AGREEMENT NAME San Juan 31-6 Unit
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 990' FNL - 990' FEL		8. FARM OR LEASE NAME San Juan 31-6 Unit
14. PERMIT NO.		9. WELL NO. 4
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6451 GR		10. FIELD AND POOL, OR WILDCAT Blanco Mesa Verde
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 4, T30N, R6W NMPM
		12. COUNTY OR PARISH Rio Arriba
		13. STATE New Mexico



16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Plugged and abandoned the well as follows:

1-23-75: Found 2-3/8" tubing stuck. Could not get below 4782' with sinker bar. Shot tubing off at 4770' with 2" jet shot. Circulated well and spotted 125 sacks cement @ 4770'.

Perforated 4 holes @ 2580'. Spotted 50 sacks cement down tubing @ 2580' and squeezed.

Shot 7" casing off @ 389' & recovered same. Spotted 50 sacks cement down tubing on top of stub @ 389'.

Spotted 25 sacks cement @ base of 9-5/8" surface pipe.

Placed 15 sacks cement @ surface with a 4" x 4' P&A marker.

Operations completed 2-4-75.

Due to weather and road conditons we have not been able to complete location clean-up. An additional Sundry notice will be filed as soon as the clean up is complete.

18. I hereby certify that the foregoing is true and correct

SIGNED

O.B. Whitenburg
O.B. Whitenburg

TITLE **Production & Drilling Eng.**

DATE **3-21-75**

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE