Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPRO	V P D
Budget Bureau No.	1004-0135
Expires: March 3	1 1993

5. Lease Designation and Serial No.

SF-079487A

Do not use this form for proposals to drill o	or to deepen or reentry to a different reservoir. PERMIT - " for such Grandells 2 PM 2: 49	6. If Indian, Allottee or Tribe Name
	IN TRIPLICATE 070 FARMINGTON, NM	7. If Unit or CA, Agreement Designation San Juan 30-4 Unit
1. Type of Well Oil X Gas Well Other 2. Name of Operator ENERGEN RESOURCES CORPORATION	DECEIVED AUG 0 9 1989	8. Well Name and No. San Juan 30-4 Unit 40 9. API Well No.
 Address and Telephone No. 2198 Bloomfield Highway, Farmington Location of Well (Footage, Sec., T., R., M., or Survey Des 2450' FSL, 2270' FEL, Sec. 21, T30N 	, NM 87401 ON GON DIV	30-039-25538 10. Field and Pool, or exploratory Area Basin Ft/E. Blanco PC/MV 11. County or Parish, State Rio Arriba NM
12. CHECK APPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTICE, REPORT,	11110
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent Subsequent Report Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing X Other Test	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of malitiple completion on Well Completion or Recompletion Report and Log form.)
Describe Proposed or Completed Operations (Clearly state all give subsurface locations and measured and true vert	pertinent details, and give pertinent dates, including estimated date of startical depths for all markers and zones pertinent to this work.)*	ng any proposed work. If well is directionally drille

In reference to NMSF-079487A (WC) it is intended to test each zone for production as follows:

- 1. RU swab unit swab test Mesaverde.
- 2. If no show of gas, trip out of hole with both strings of tubing.
- 3. TIH with RBP and packer. Swab test PC. If no show of gas, squeeze cement with sufficient amount to isolate zone.
- 4. Pull up hole. Swab test Fruitland Coal. If no show of gas, squeeze cement.
- 5. TIH and drill out cement to top of liner. Test casing. TOH.
- 6. Convert well to water disposal in Mesaverde.

I hereby certify that the foregoing is true and correct Signed Monico Jaylor	Title Production Assistant	Date 7/9/99
(This space for Federal or State office use) Approved by S Duane W. Spencer	Team Lead, Petroleum Menagement	Date AUG - 5 1999
Conditions of approval, if any:		

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.