| Form: 9-361 a (Feb. 1987) | | | | | | | |
|------------------------------|--|--|--|--|--|--|--|
| | | | | | | | |
| | | | | | | | |
| - | | | | | | | |

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

| | a. = | |
|--------|-------------|--------------------|
| Budget | Bure on No. | 42- X 358.4 |
| Porm A | poroważ. | |

San Just 30-5 Unit

| | AND REPORTS ON WELLS | יוס וב ע איי |
|--|--|--------------|
| NOTICE OF INTENTION TO BRILL | SUBSEQUENT REPORT OF WATER SHUT-OFF | LIN 291196 |
| NOTICE OF INTENTION TO CHANGE PLANS | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING. | |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | | FOROGICAL S |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | FADMI | NGTON, NEW A |
| NOTICE OF ATTENTION TO SHOOT OF ACIDIZE | The state of the s | |
| MOTICE OF INTENTION TO PULL OR ALTER CASING | SUPPLEMENTARY WELL HISTORY | * |
| *************************************** | | |
| (INDICATE ABOVE BY CHECK M | MARK NATURE OF REPORT, NOTICE, OR OTHER DATA) | |
| | June 28 | 19 64 |
| Well No. 2-29 is located 900 ft. fr | rom N line and 1045 ft. from E line of | sec. 29 |
| | 5-W N.M.P.M. | |
| (14 Sec. and Sec. No.) (Twp.) | (Kange) (Meridian) | |
| *** double management of the contract of the c | nty or Subdivision (State or Territory) | |
| ing points, and s | w sizes, weights, and lengths of proposed casings; indicate mud- all other important proposed work) | |
| Will vas pla | ugged & abandoned in the following | ender: |
| 1. Spotted 270 sacks cement plug t 2. Pulled tubing. | | |
| 1. Spotted 270 sacks cement plug to 2. Pulled tubing. | ed 37 sacks cement plug across casi | eg stub. |
| 1. Spetted 270 sacks cement plug to 2. Pulled tubing. 3. Shot 7" casing @ 1120'. Spotted 4. Pulled 7" casing. Spotted 10 s | ed 37 sacks cement plug across casissack cement plug in surface. RLULI JUL 2. OIL CON. | estab. |
| Spotted 270 sacks cement plug to 2. Pulled tubing. Shot 7" casing @ 1120'. Spotted 10 sacks the pulled 7" casing. Spotted 10 sacks the pulled 7" dry hole marker. | ed 37 sacks cement plug across casissack cement plug in surface. | |
| 1. Spotted 270 sacks cement plug to 2. Pulled tubing. 3. Shot 7" casing @ 1120'. Spotted to 4. Pulled 7" casing. Spotted 10 said with a 4" dry hole marker. I understand that this plan of work must receive appearance. | ed 37 sacks cement plug across casis sack cement plug in surface. FRILLI JUL 2 OIL CON. DIST. al in writing by the Geological Survey before operations may be | |
| 1. Spotted 270 sacks cement plug to 2. Palled tubing. 3. Shot 7" casing @ 1120'. Spotted 4. Pulled 7" casing. Spotted 10 start at a dry hole marker. I understand that this plan of work must receive appearance. | ed 37 sacks cement plug across casis sack cement plug in surface. FRILLI JUL 2 OIL CON. DIST. al in writing by the Geological Survey before operations may be | |
| 1. Spotted 270 sacks cement plug to 2. Pulled tubing. 3. Shot 7" casing @ 1120'. Spotted to 4. Pulled 7" casing. Spotted 10 state and the dry hole marker. I understand that this plan of work must receive appearance of the plan of the plan of work must receive appearance of the plan of the pla | ed 37 sacks cement plug across casis sack cement plug in surface. FRILLI JUL 2 OIL CON. DIST. al in writing by the Geological Survey before operations may be | |