

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. SF-078931-B (CA #8561)
2. NAME OF OPERATOR DUGAN PRODUCTION CORP.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 208, Farmington, NM 87499		7. UNIT AGREEMENT NAME Central Cha Cha Unit
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2130' FNL & 1850' FEL		8. FARM OR LEASE NAME Central Cha Cha Unit
14. PERMIT NO.		9. WELL NO. 3
15. ELEVATIONS (Show whether DP, ST, CR, etc.) 5866' GL; 5877' RKB		10. FIELD AND POOL, OR WILDCAT Cha Cha Gallup
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 31, T29N, R13W, NMPM
		12. COUNTY OR PARISH San Juan
		13. STATE NM

15. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	_____	PULL OR ALTER CASING	_____
FRACTURE TREAT	_____	MULTIPLE COMPLETE	_____
SHOOT OR ACIDIZE	_____	ABANDON*	☒
REPAIR WELL	_____	CHANGE PLANS	_____
(Other)	_____		_____

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	_____	REPAIRING WELL	_____
FRACTURE TREATMENT	_____	ALTERING CASING	_____
SHOOTING OR ACIDIZING	_____	ABANDONMENT*	_____
(Other)	_____		_____

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Plan to Plug and Abandon as follows:

- Spot plug across top of Gallup perms ^{5136'} 5493' - 5593'
 - Spot 100' cement plug over top of Mesaverde formation ^{plug 3100' - 3000' mv inside & out} 2370' - 2470'
 - Spot 100' plug 1450' - 1550' across Pictured Cliffs formation ^{plug 1350-1250' Fr}
 - Spot surface plug ²¹⁰ 200' to surface ^{inside & out}
- Install dry hole marker and restore location

RECEIVED
BLM MAIL ROOM

88 FEB 29 PM 12:50

FARMINGTON RESOURCE AREA
FARMINGTON, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Vice President

DATE

APR 2/26/88

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

MAR 0 1988

CONDITIONS OF APPROVAL, IF ANY: