UNITED STATES SUBMIT IN TRIPLICATES (Other instructions on re(Other ins

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.) 7. UNIT AGREEMENT NAME San Juan 30-5 Unit San Juan 30-5 Unit Northwest Pipeline Corporation 8. FARM OR LEASE NAME Northwest Pipeline Corporation 9. WELL NO. P.O. Box 90 Farmington, New Mexico 87401 1. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* 10. FIELD AND POOL, OR WILDCAT		- - -	SEOLOGICAL SURVEY	(1011 verse alue)	SF 078739
TOTAL GARDON NAME OIL GARD WELL NO OTHER 2. NAME OF OPERATOR NORTHWEST Pipeline Corporation 8. ADDERES OF OPERATOR P.O. BOX 90 Farmington, New Mexico 87401 4. LOCATION OF WILL (Report location clearly and in accordance with any State requirements.* See also appear 17 below.) At surface 990' FNL and 990' FEL 990' FNL and 990' FEL 16. ELEVATIONS (Show whether DF, RT, GR, etc.) 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER BRUT-OFF FRACTURE TREAT BROOT OR ACIDIES REPAIR WELL CHANGE FLANS (Other) 17. DESCRIBE PROPOSED OR COMPLETED DEPRATIONS (Clearly state all pertinent details, and give pertinents. Including estimated date of starting proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones performed to Spotted 100 saxs (200') from 2550' to 5400'. Spotted 70 saxs (200') from 2550' to 5400'. Spotted 70 saxs (200') from 2050' to 1800'. 3-25-76 Spotted 100 saxs (200') from 2050' to 1800'. Spotted 41 saxs (150') from 750' to 600'. Spotted 21 saxs (50') from 200' to 150'.	(Do no	SUNDRY NOT t use this form for propose Use "APPLICA	ICES AND REPORTS tale to drill or to deepen or plus ATION FOR PERMIT—" for such	ON WELLS g back to a different reservoir. proposais.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Northwest Pipeline Corporation 8. Alder of Persons Northwest Pipeline Corporation 8. Alder of Persons Northwest Pipeline Corporation 8. Alder of Persons P.O. Box 90 Farmington, New Mexico 87401 4. Locardon of Will, (Report location clearly and in accordance with any State requirements.* See also paper 17 below.) At surface 990' FNL and 990' FEL 10. First was paper 17 below. 11. Sec., R., R., M., OB BLEAK AND STURYEY OR AREA Sec. 22, T30N, R51 14. Ferrity No. 15. Elevations (Show whether Dr. RT, GR. etc.) 66675' Rio Arriba N.M., 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: WATER SHOT-OFF FRACTURE TREAT SHOOT OR ACIDIZED ARABODN' REPAIR WELL CHAPTER OF PLANS (Other) 7. DENORTHE PROPOSED OR CONFLETE OF PLANS REPAIR WELL CHAPTER OF PLANS (Other) REPAIR METATER OTHER ALTER OTHER REPAIR METATER ALTER OTHER REPAIR METATER ALTER OTHER REPAIR METATER ALTER OTHER REPAIR METATER ALTER OTHER REPAIR METATER ALTER OTHER REPAIR METATER ALTER OTHER REPAIR METATER ALTER OTHER REPAIR METATER ALTER OTHER REPAIR METATER ALTER OTHER REPAIR METATER ALTER OTHER REPAIR METATER ALTER OTH					7. UNIT AGREEMENT NAME
Northwest Pipeline Corporation 8. Address 87 o'relator P.O. Box 90 Farmington, New Mexico 87401 1. Mecanism or well (Report location clearly and in accordance with any State requirements.* See all pages 17 below.) 990' FNL and 990' FEL 10. FIREM AND POOL, OR WILLDEAT Blanco Mess Verde 11. SEC., F. B. M., OR BLK, AND SURVEY OR AREA AND NOTICE OF INTENTION TO: TEST WATER SHUT-OFF PLACTURE TREAT MULLIPLE COMPLETE ARABADON* REPAIR WELL COMPLETE ARABADON* CHANGE PLANS COUNTY REPORT OF: REPAIR WELL COMPLETE TREATMENT ALTERING CASING MULLIPLE COMPLETE REPAIR WELL COMPLETE OF PRACTICES COMPLETED OF PRACTICES CHANGE PLANS COUNTY REPORT OF COMPLETED OF PRACTICES CHANGE PLANS COUNTY REPORT OF COUNTY PRACTICES COUNTY OR ACTORISE CHANGE PLANS COUNTY REPORT OF COUNTY PRACTICES TREATMENT ALTERING CASING ANABODAMENT* X ADARDONS COUNTY PRACTICES CHANGE PLANS COUNTY OR PARISH 13. STATE RIO ATTIBLE ON AREA AND N. M. 17. PESCENIAL PROPOSED OR COUNTY PLANS CHANGE PLANS COUNTY OR PARISH 13. STATE RIO ATTIBLE ON AREA CHANGE PLANS COUNTY OR PARISH 13. STATE RIO ATTIBLE ON AREA ANABODAMENT* X ADARDAMENT X		GAS TO OTHER			San Juan 30-5 Unit
P.O. Box 90 Farmington, New Mexico 87401 1 1 1 10. FIRED AND FOOL, OR WILLOW SEC also space 17 below.) At surface 990 FNL and 990 FEL 10. FIRED AND FOOL, OR WILDOW 990 FNL and 990 FEL 11. FRANT NO. 16. ELEVATIONS (Show whether DF, RT, OR, etc.) 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHOT-OFF FLANS SHOOT OR ACIDIZE REPART WILL CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS CHORNE TROPOSED OR COMPLETED OPERATIONS (Clearly state all pertitent details, and give pertinent dates, including completion on Well Completion work.)* 3-24-76 Pulled tubing 3-25-76 Perfed 2 squeeze holes at base of PC (3716') and 0jo Alamo (2920') 3-26-76 Spotted 50 sxs (200') from 3720' to 3520' and squeezed. 3-27-76 Spotted 70 sxs (200') from 2720' to 3520' and squeezed. 3-29-76 Spotted 100 sxs (250') from 2050' to 1800'. 3-30-76 Shot 7" @ 742'. Pulled csg. 3-31-76 Spotted 41 sxs (150') from 750' to 600'. Spotted 21 sxs (50') from 200' to 150'.		EBATOR			8. FARM OR LEASE NAME
P.O. Box 90 Farmington, New Mexico 87401 4. Incavina of with (Report location clearly and in accordance with any State requirements." See also space 17 below.) At surface 990' FNL and 990' FEL 10. FIELD AND FOOL, OR WILDCAY BURNET OR ARDA See. 22,T30N, R51 14. FERRIT NO. 16. ELEVATIONS (Show whether DF, RT, GR, etc.) 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF PRACTURE TREAT SHOOT OR ACTINIZE REPAIR WILL (Other) 17. DESCRIBE IMPOSED OR COMPLETED OFFRATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting rent to this work.)* 3-24-76. Pulled tubing 3-25-76 Perfed 2 squeeze holes at base of PC (3716') and 0jo Alamo (2920') 3-26-76 Spotted 50 sxs (150') from 2550' to 5400'. Spotted 70 sxs (200') from 2920' to 3720' and squeezed. 3-27-76 Spotted 100 sxs (250') from 2920' to 2720' and squeezed. 3-29-76 Spotted 41 sxs (150') from 2920' to 1800'. 3-30-76 Spotted 41 sxs (150') from 2050' to 1800'. 3-31-76 Spotted 41 sxs (150') from 750' to 600'. Spotted 21 sxs (50') from 200' to 150'.	North	nwest Pipeline C	Corporation		San Juan 30-5 Unit
See also space 17 below.) At surface 990' FNL and 990' FEL 11. BEC, T. B., M., OR BEE. AND SURVEY OR AREA Sec. 22, T30N, R50 14. FERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF PULL OR ALTER CASING MULTIPLE COMPLETE SHOOT OR ACIDIZE REPAIR WELL CHANGE PLANS (Other)	8. ADDRESS OF	OPERATOR			9. WELL NO.
Blanco Mesa Verde 990' FNL and 990' FEL 11. SEC., T., R., M., OR BLE. AND SUBER OR ARBIET OR ARBA Sec. 22, T30N, R5 Sec. 22, T30N, R5 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF PRACTURE TREAT SHOOT OR ACIDIZE REPAIRING WELL (Other) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting rent to this work.) 3-24-76 Pulled tubing 3-25-76 Perfed 2 squeeze holes at base of PC (3716') and 0jo Alamo (2920') 3-26-76 Spotted 70 sxs (200') from 3720' to 3520' and squeezed. 3-27-76 Spotted 70 sxs (200') from 2920' to 2720' and squeezed. 3-29-76 Spotted 100 sxs (250') from 2920' to 2720' and squeezed. 3-3-30-76 Spotted 41 sxs (150') from 750' to 600'. Spotted 21 sxs (50') from 200' to 150'. Spotted 41 sxs (150') from 750' to 600'. Spotted 21 sxs (50') from 200' to 150'.	P.O.	Box 90 Farmi	1		
990' FNL and 990' FEL 11. SEC. 7. E. M., OE BLE. AND SURVEY OR ALDA SEC. 22, T30N, R51 14. Permit No. 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data Notice of Intention to: TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF PEACTURE TREAT WILTERILE COMPLETE SHOOT OR ACIDIZE ABANDON'S CHANGE PLANS (Other) REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all perticent details, and give pertinent dates, including estimated date of starting proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perticent details. Spotted 50 sxs (150') from 5550' to 5400'. Spotted 70 sxs (200') from 3720' to 3520' and squeezed. 3-27-76 Spotted 100 sxs (250') from 2920' to 2720' and squeezed. 3-29-76 Spotted 100 sxs (250') from 2920' to 2720' and squeezed. 3-30-76 Shot 7" @ 742'. Pulled csg. 3-31-76 Spotted 41 sxs (150') from 750' to 600'. Spotted 21 sxs (50') from 200' to 150'.	See also spa	F WELL (Report location cl ace 17 below.)	10. FIELD AND POOL, OR WILDCAT		
Sec. 22, T30N, R51 14. FERMIT NO. 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF FEACTURE TREAT SHOOT OR ACIDIZED REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertibent details, and give pertinent dates, including estimated date of starting nent to this work.) 3-24-76 Pulled tubing 3-25-76 Perfed 2 squeeze holes at base of PC (3716') and 0 jo Alamo (2920') 3-26-76 Spotted 50 sxs (150') from 3720' to 3520' and squeezed. 3-27-76 Spotted 70 sxs (200') from 2920' to 2720' and squeezed. 3-29-76 Spotted 100 sxs (250') from 2050' to 1800'. 3-30-76 Spotted 41 sxs (150') from 750' to 600'. Spotted 21 sxs (50') from 200' to 150'.	At surface		_		Blanco Mesa Verde
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting; proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones penetro to this work.) 3-24-76 Pulled tubing 3-25-76 Perfed 2 squeeze holes at base of PC (3716') and 0jo Alamo (2920') 3-26-76 Spotted 50 sxs (150') from 5550' to 5400'. Spotted 70 sxs (200') from 3720' to 3520' and squeezed. 3-27-76 Spotted 100 sxs (250') from 2920' to 2720' and squeezed. 3-29-76 Spotted 100 sxs (250') from 2920' to 2720' and squeezed. 3-30-76 Shot 7" @ 742'. Pulled csg. 3-31-76 Spotted 41 sxs (150') from 750' to 600'. Spotted 21 sxs (50') from 200' to 150'.		990' FNL a	and 990' FEL		SURVEY OR ARDA
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting; proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones penetro to this work.) 3-24-76 Pulled tubing 3-25-76 Perfed 2 squeeze holes at base of PC (3716') and 0jo Alamo (2920') 3-26-76 Spotted 50 sxs (150') from 5550' to 5400'. Spotted 70 sxs (200') from 3720' to 3520' and squeezed. 3-27-76 Spotted 100 sxs (250') from 2920' to 2720' and squeezed. 3-29-76 Spotted 100 sxs (250') from 2920' to 2720' and squeezed. 3-30-76 Shot 7" @ 742'. Pulled csg. 3-31-76 Spotted 41 sxs (150') from 750' to 600'. Spotted 21 sxs (50') from 200' to 150'.					Sec. 22.T30N. R5W
Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF PULL OR ALTER CASING NULTIPLE COMPLETE ABANDON' SHOOT OR ACIDIZE REPORT OR ACIDIZE CHANGE PLANS (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones per next to this work.)* 3-24-76. Pulled tubing 3-25-76 Perfed 2 squeeze holes at base of PC (3716') and Ojo Alamo (2920') 3-26-76 Spotted 50 sxs (150') from 5550' to 5400'. Spotted 70 sxs (200') from 3720' to 3520' and squeezed. 3-27-76 Spotted 70 sxs (200') from 2920' to 2720' and squeezed. 3-29-76 Spotted 100 sxs (250') from 2920' to 1800'. 3-30-76 Shot 7" @ 742'. Pulled csg. 3-31-76 Spotted 41 sxs (150') from 750' to 600'. Spotted 21 sxs (50') from 200' to 150'.	14. PERMIT NO.		15. ELEVATIONS (Show whether	DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
NOTICE OF INTENTION TO: TEST WATER SHUT-OFF PRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent details. 3-24-76. Pulled tubing 3-25-76 Perfed 2 squeeze holes at base of PC (3716') and Ojo Alamo (2920') 3-26-76 Spotted 50 sxs (150') from 5550' to 5400'. Spotted 70 sxs (200') from 3720' to 3520' and squeezed. 3-27-76 Spotted 70 sxs (200') from 2920' to 2720' and squeezed. 3-29-76 Spotted 100 sxs (250') from 2920' to 2720' and squeezed. 3-29-76 Spotted 40 sxs (250') from 2950' to 1800'. 3-30-76 Shot 7" @ 742'. Pulled csg. 3-31-76 Spotted 41 sxs (150') from 750' to 600'. Spotted 21 sxs (50') from 200' to 150'.			6675'		Rio Arriba N.M.
NOTICE OF INTENTION TO: TEST WATER SHUT-OFF PRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent details. 3-24-76. Pulled tubing 3-25-76 Perfed 2 squeeze holes at base of PC (3716') and Ojo Alamo (2920') 3-26-76 Spotted 50 sxs (150') from 5550' to 5400'. Spotted 70 sxs (200') from 3720' to 3520' and squeezed. 3-27-76 Spotted 70 sxs (200') from 2920' to 2720' and squeezed. 3-29-76 Spotted 100 sxs (250') from 2920' to 2720' and squeezed. 3-29-76 Spotted 40 sxs (250') from 2950' to 1800'. 3-30-76 Shot 7" @ 742'. Pulled csg. 3-31-76 Spotted 41 sxs (150') from 750' to 600'. Spotted 21 sxs (50') from 200' to 150'.	16.	Check Ar	propriate Box To Indicate	Nature of Notice, Report, or	Other Data
PRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones per nent to this work.)* 3-24-76 Pulled tubing 3-25-76 Perfed 2 squeeze holes at base of PC (3716') and Ojo Alamo (2920') 3-26-76 Spotted 50 sxs (150') from 5550' to 5400'. Spotted 70 sxs (200') from 3720' to 3520' and squeezed. 3-27-76 Spotted 70 sxs (200') from 2920' to 2720' and squeezed. 3-29-76 Spotted 100 sxs (250') from 2050' to 1800'. 3-30-76 Shot 7" @ 742'. Pulled csg. 3-31-76 Spotted 41 sxs (150') from 750' to 600'. Spotted 21 sxs (50') from 200' to 150'.		•	•		
PRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones per nent to this work.)* 3-24-76 Pulled tubing 3-25-76 Perfed 2 squeeze holes at base of PC (3716') and Ojo Alamo (2920') 3-26-76 Spotted 50 sxs (150') from 5550' to 5400'. Spotted 70 sxs (200') from 3720' to 3520' and squeezed. 3-27-76 Spotted 70 sxs (200') from 2920' to 2720' and squeezed. 3-29-76 Spotted 100 sxs (250') from 2050' to 1800'. 3-30-76 Shot 7" @ 742'. Pulled csg. 3-31-76 Spotted 41 sxs (150') from 750' to 600'. Spotted 21 sxs (50') from 200' to 150'.			DULL OF ALTER CASING	WATER CRITICA	DEPAIRING WELL
BHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 3-24-76 Pulled tubing 3-25-76 Perfed 2 squeeze holes at base of PC (3716') and Ojo Alamo (2920') 3-26-76 Spotted 50 sxs (150') from 5550' to 5400'. Spotted 70 sxs (200') from 3720' to 3520' and squeezed. 3-27-76 Spotted 70 sxs (200') from 2920' to 2720' and squeezed. 3-29-76 Spotted 100 sxs (250') from 2050' to 1800'. 3-30-76 Shot 7" @ 742'. Pulled csg. 3-31-76 Spotted 41 sxs (150') from 750' to 600'. Spotted 21 sxs (50') from 200' to 150'.					_
REPAIR WELL (Other) CHANGE PLANS (Other) (Note: Report results of multiple completion on Well Completion of Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones per nent to this work.) 3-24-76. Pulled tubing 3-25-76. Perfed 2 squeeze holes at base of PC (3716') and Ojo Alamo (2920') 3-26-76. Spotted 50 sxs (150') from 5550' to 5400'. Spotted 70 sxs (200') from 3720' to 3520' and squeezed. 3-27-76. Spotted 70 sxs (200') from 2920' to 2720' and squeezed. 3-29-76. Spotted 100 sxs (250') from 2050' to 1800'. 3-30-76. Shot 7'' @ 742'. Pulled csg. 3-31-76. Spotted 41 sxs (150') from 750' to 600'. Spotted 21 sxs (50') from 200' to 150'.					— —
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones per nent to this work.)* 3-24-76 Pulled tubing 3-25-76 Perfed 2 squeeze holes at base of PC (3716') and Ojo Alamo (2920') 3-26-76 Spotted 50 sxs (150') from 5550' to 5400'. Spotted 70 sxs (200') from 3720' to 3520' and squeezed. 3-27-76 Spotted 70 sxs (200') from 2920' to 2720' and squeezed. 3-29-76 Spotted 100 sxs (250') from 2050' to 1800'. 3-30-76 Shot 7" @ 742'. Pulled csg. 3-31-76 Spotted 41 sxs (150') from 750' to 600'. Spotted 21 sxs (50') from 200' to 150'.		[_	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones per nent to this work.)* 3-24-76 Pulled tubing 3-25-76 Perfed 2 squeeze holes at base of PC (3716') and Ojo Alamo (2920') 3-26-76 Spotted 50 sxs (150') from 5550' to 5400'. Spotted 70 sxs (200') from 3720' to 3520' and squeezed. 3-27-76 Spotted 70 sxs (200') from 2920' to 2720' and squeezed. 3-29-76 Spotted 100 sxs (250') from 2050' to 1800'. 3-30-76 Shot 7" @ 742'. Pulled csg. 3-31-76 Spotted 41 sxs (150') from 750' to 600'. Spotted 21 sxs (50') from 200' to 150'.	(Other)	<u> </u>		(Note: Report result Completion or Recom	s of multiple completion on Well
3-25-76 Perfed 2 squeeze holes at base of PC (3716') and Ojo Alamo (2920') 3-26-76 Spotted 50 sxs (150') from 5550' to 5400'. Spotted 70 sxs (200') from 3720' to 3520' and squeezed. 3-27-76 Spotted 70 sxs (200') from 2920' to 2720' and squeezed. 3-29-76 Spotted 100 sxs (250') from 2050' to 1800'. 3-30-76 Shot 7" @ 742'. Pulled csg. 3-31-76 Spotted 41 sxs (150') from 750' to 600'. Spotted 21 sxs (50') from 200' to 150'.	proposed	work. If well is direction	RATIONS (Clearly state all pertic smally drilled, give subsurface lo	ent details, and give pertinent dates	s, including estimated date of starting an
3-25-76 Perfed 2 squeeze holes at base of PC (3716') and Ojo Alamo (2920') 3-26-76 Spotted 50 sxs (150') from 5550' to 5400'. Spotted 70 sxs (200') from 3720' to 3520' and squeezed. 3-27-76 Spotted 70 sxs (200') from 2920' to 2720' and squeezed. 3-29-76 Spotted 100 sxs (250') from 2050' to 1800'. 3-30-76 Shot 7" @ 742'. Pulled csg. 3-31-76 Spotted 41 sxs (150') from 750' to 600'. Spotted 21 sxs (50') from 200' to 150'.	3_2/_76	Pulled tubing			
3-26-76 Spotted 50 sxs (150') from 5550' to 5400'. Spotted 70 sxs (200') from 3720' to 3520' and squeezed. 3-27-76 Spotted 70 sxs (200') from 2920' to 2720' and squeezed. 3-29-76 Spotted 100 sxs (250') from 2050' to 1800'. 3-30-76 Shot 7" @ 742'. Pulled csg. 3-31-76 Spotted 41 sxs (150') from 750' to 600'. Spotted 21 sxs (50') from 200' to 150'.		Perfed 2 salles	eze holes at base o	f PC (3716') and Oio A	Alamo (2920¹)
Spotted 70 sxs (200') from 3720' to 3520' and squeezed. 3-27-76 Spotted 70 sxs (200') from 2920' to 2720' and squeezed. 3-29-76 Spotted 100 sxs (250') from 2050' to 1800'. 3-30-76 Shot 7" @ 742'. Pulled csg. 3-31-76 Spotted 41 sxs (150') from 750' to 600'. Spotted 21 sxs (50') from 200' to 150'.					
3-27-76 Spotted 70 sxs (200') from 2920' to 2720' and squeezed. 3-29-76 Spotted 100 sxs (250') from 2050' to 1800'. 3-30-76 Shot 7" @ 742'. Pulled csg. 3-31-76 Spotted 41 sxs (150') from 750' to 600'. Spotted 21 sxs (50') from 200' to 150'.	3 20 70				1.
3-29-76 Spotted 100 sxs (250') from 2050' to 1800'. 3-30-76 Shot 7" @ 742'. Pulled csg. 3-31-76 Spotted 41 sxs (150') from 750' to 600'. Spotted 21 sxs (50') from 200' to 150'.	3-27-76				
3-30-76 Shot 7" @ 742'. Pulled csg. 3-31-76 Spotted 41 sxs (150') from 750' to 600'. Spotted 21 sxs (50') from 200' to 150'.					
to 150'.	3-30-76				
	3-31-76		s (150') from 750'	to 600'. Spotted 21 s	xs (50') from 200'
	4-1-76		plug at surface an	d installed a 4' X 4"	dry hole marker.
			TOTAL A		

RELL	VED / APR 6 1976	
APR OIL COI	- 407C	
18. I hereby certify that the foregoing is true and correct SIGNED D.H. Maroncelli		DATE 4-5-76
(This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE	_ DATE

*See Instructions on Reverse Side