

October 23, 1981

Amoco Production Company
501 Airport Drive
Farmington, NM 87401

Re: USG 19 #17 I-19-29N-16W

Gentlemen:

Annual packer tests on the above-referenced injection or SWD well indicate a packer or tubing leak.

In order to insure the protection of hydrocarbon bearing and fresh water zones, you are hereby directed to initiate remedial action within sixty days.

Yours truly,

Jeff A. Edmister
Deputy Inspector

JAE:gc

cc: ~~Operator file~~ well file
Prentice Childs