



(SUBMIT IN TRIPPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

30-045-0813

Budget Bureau No. 42-R368.4.
Approval expires 12-31-60.

Land Office Las Cruces, N.M.

Lease No. SF 078716

Unit New Mexico Federal
Deep Unit

SUNDRY NOTICES AND REPORTS ON WELLS

- NOTICE OF INTENTION TO DRILL
NOTICE OF INTENTION TO CHANGE PLANS
NOTICE OF INTENTION TO TEST WATER SHUT-OFF
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL
NOTICE OF INTENTION TO SHOT OR ACIDIZE
NOTICE OF INTENTION TO PULL OR ALTER CASING
NOTICE OF INTENTION TO ABANDON WELL

- SUBSEQUENT REPORT OF WATER SHUT-OFF
 SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
 SUBSEQUENT REPORT OF ALTERING CASING
 SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
 SUBSEQUENT REPORT OF ABANDONMENT
 SUPPLEMENTARY WELL HISTORY

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 5, 1960

Well No. 1 is located 990 ft. from $\{N\}$ line and 950 ft. from $\{E\}$ line of sec. 19

NE¹, NE¹, Sec. 19
(1/4 Sec. and Sec. No.)

29-N
(Twp.)

10-W
(Range)

NMPH
(Meridian)

Undesignated (Dakota)
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

13-3/8" 36# new casing to be set at approximately 120' and cemented to surface.
4-1/2" 11.6# new casing to be set at approximately 6750'. 2 Stage collar @ 2100' and cemented with sufficient volume to circulate back to 13-3/8".
Section below 2100' cemented with sufficient volume to protect all pay zones.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Tidewater Oil Company

Address Area Office - Box 587, Hobbs, New Mexico

Distr. Office, Box 1231, Midland, Texas

Division Office, Box 1404, Houston, Texas

By J. M. Davis
Title Authorized Employee

GPO 918507

... for completing this form on the reverse side